Assignment-1

```
Gas Leakage monitoring & Damp; Alerting system for Industries
Make smart home with atleast 2 sensors and led, buzzer. In tinkercad
Int gasSensor=A1;
Int buzzer=13;
Int led=12;
Void setup()
 pinMode(A1,INPUT);
 pinMode(buzzer,OUTPUT);
 pinMode(led,OUTPUT);
Serial.begin(9600);
}
Void loop()
Int sensorValue=analogRead(gasSensor);
Serial.print("GAS LEVEL:");
Serial.println(sensorValue);
 Delay(1000);
If (sensorValue>250)
 {
  digitalWrite(buzzer,HIGH);
  digitalWrite(led,HIGH);
}
Else
{
 digitalWrite(buzzer,LOW);
 digitalWrite(led,LOW);
```

By Amarjith Arun kumar Deepak Joyal prasanna