Assignment -4


Question-1:

Write code and connections in wokwi for ultrasonic. Whenever distance is less than 100 cms send "alert" to ibm cloud and display in device recent events.

Solution:

```
#define ECHO_PIN 2
#define TRIG_PIN 3
#define organization = "mmbh4c"
#define deviceType = "Ultrasonic"
#define deviceId = "pga460_sensor"
#define authMethod = "use-token-auth"
#define authToken = "123456789"
void setup() {
Serial.begin(9600);
 pinMode(TRIG_PIN, OUTPUT);
pinMode(ECHO_PIN, INPUT);
}
float readDistanceCM() {
digitalWrite(TRIG_PIN, LOW);
delayMicroseconds(2);
digitalWrite(TRIG_PIN, HIGH);
delayMicroseconds(10);
digitalWrite(TRIG_PIN, LOW); int
duration = pulseIn(ECHO_PIN, HIGH);
return duration * 0.034 / 2;
}
```

```
void loop() { float distance =
readDistanceCM(); if(distance <=
100)
{
    Serial.println("person detected ");
}
else{
Serial.print("Measured distance: ");
Serial.println(readDistanceCM());
}
delay(1000);
}</pre>
```



Wokwi Link: https://wokwi.com/projects/348690219143266899