Date:17/11/2022

Team ID: PNT2022TMID46067

## **Connecting Sensors with Arduino**

```
#include "Arduino.h"
#include "dht.h"
#include "SoilMoisture.h"
#define dht_apin A0
const int sensor_pin = A1; //soil moisture int pin_out = 9;
dht DHT; int c=0; void setup()
{
pinMode(2, INPUT); //Pin 2 as INPUT pinMode(3, OUTPUT); //PIN
3 as OUTPUT pinMode(9, OUTPUT);//output for pump
}
void loop()
{
 if (digitalRead(2) == HIGH)
 digitalWrite(3, HIGH);
                                     // turn the LED/Buzz ON
 delay(10000); // wait for 100 msecond digitalWrite(3, LOW); // turn the
 LED/Buzz OFF delay(100);
 }
  Serial.begin(9600);
    delay(1000);
   DHT.read11(dht_apin);
                                  //temprature
                                                        float
 h=DHT.humidity;
```

```
float
                  t=DHT.temperature;
 delay(5000);
                  Serial.begin(9600);
 float moisture_percentage; int
 sensor_analog;
                     sensor_analog
 analogRead(sensor_pin);
 moisture_percentage = (100 - ((sensor\_analog/1023.00) * 100));
 float m=moisture_percentage; delay(1000); if(m<40)//pump
 \{ while(m<40) \}
 digitalWrite(pin_out,HIGH);
                                //open pump sensor_analog =
 analogRead(sensor_pin);
 moisture_percentage = (100 - ((sensor\_analog/1023.00) * 100)
 ); m=moisture_percentage; delay(1000);
 }
 digitalWrite(pin_out,LOW);
                                              //closepump
 if(c>=0)
 mySerial.begin(9600);
                                          delay(15000);
 Serial.begin(9600); delay(1000);
 Serial.print("\r"); delay(1000);
 Serial.print((String)"update-
>"+(String)"Temprature="+t+(String)"Humidity="+h+(String)
)"Moisture="+m); delay(1000);
   }
}
```

## Circuit Diagram

