Assignmentt 1

Batch No: B1-1M3E

Build a python code ,assume u get temperature and humidity values (generated with random function to a variable) and write a condition to continuously detect a alarm in case of

```
# import standard python modules.
import time
# import adafruit dht library.
import Adafruit_DHT
# import Adafruit IO REST client.
from Adafruit_IO import Client, Feed
# Delay in-between sensor readings, in seconds. DHT_READ_TIMEOUT = 5
# Pin connected to DHT22 data pin
DHT_DATA_PIN = 26
# Set to your Adafruit IO key.
# Remember, your key is a secret,
# so make sure not to publish it when you publish this code! ADAFRUIT_IO_KEY =
'YOUR_AIO_KEY'
# Set to your Adafruit IO username.
# (go to https://accounts.adafruit.com to find your username).
 ADAFRUIT_IO_USERNAME = 'YOUR_AIO_USERNAME'
```

```
# Create an instance of the REST client.
aio = Client(ADAFRUIT_IO_USERNAME, ADAFRUIT_IO_KEY)
# Set up Adafruit IO Feeds.
temperature_feed = aio.feeds('temperature') humidity_feed =
aio.feeds('humidity')
# Set up DHT22 Sensor.
dht22_sensor = Adafruit_DHT.DHT22
while True:
    humidity, temperature = Adafruit_DHT.read_retry (dht22_sensor,
DHT_DATA_PIN)
    if humidity is not None and temperature is not None:
print('Temp={0:0.1f}*C Humidity={1:0.1f}%'.format(temperature, humidity))
    # Send humidity and temperature feeds to Adafruit IO
    temperature = '%.2f'%(temperature)
     humidity = '%.2f'%(humidity)
                                    aio.send(temperature_feed.key,
str(temperature)) aio.send(humidity feed.key, str(humidity))
else:
     print('Failed to get DHT22 Reading, trying again in ', DHT_READ_TIMEOUT,
'seconds')
# Timeout to avoid flooding Adafruit IO time.sleep(DHT_READ_TIMEOUT)
```