## FINAL CODE

TEAM ID	PNT2022TMID24189
PROJECT NAME	GAS LEAKAGE MONITORING AND
	ALERTING SYSTEM FOR INDUSTRIES

```
#include <LiquidCrystal.h>
LiquidCrystal lcd(5,6,8,9,10,11);
int redled = 2;
int greenled = 3;
int buzzer = 4;
int sensor = A0;
int sensorThresh = 400;
void setup()
{
pinMode(redled, OUTPUT);
pinMode(greenled,OUTPUT);
pinMode(buzzer,OUTPUT);
pinMode(sensor,INPUT);
Serial.begin(9600);
lcd.begin(16,2);
}
void loop()
 int analogValue = analogRead(sensor);
```

```
Serial.print(analogValue);
if(analogValue>sensorThresh)
{
 digitalWrite(redled,HIGH);
 digitalWrite(greenled,LOW);
 tone(buzzer,1000,10000);
 lcd.clear();
 lcd.setCursor(0,1);
 lcd.print("ALERT");
 delay(1000);
 lcd.clear();
 lcd.setCursor(0,1);
 lcd.print("EVACUATE");
 delay(1000);
}
else
 digitalWrite(greenled,HIGH);
 digitalWrite(redled,LOW);
 noTone(buzzer);
 lcd.clear();
 lcd.setCursor(0,0);
 lcd.print("SAFE");
 delay(1000);
 lcd.clear();
```

```
lcd.setCursor(0,1);
lcd.print("ALL CLEAR");
delay(1000);
}
```