import time import RPi.GPIO as GPIO GPIO.setmode(GPIO.BOARD) GPIO.setup(11, GPIO.OUT) while True: GPIO.output(11,True) time.sleep(1) GPIO.output(11,False) time.sleep(1)

coding for blinking led