untitled ð File Edit Format Run Options Window Help import RPi. GPIO as GPIO import time import signal import sys GPIO.setmode (GPIO.BCM) GPIO.setup (9, GPIO.OUT) GPIO.setup (10, GPIO.OUT) GPIO.setup (11, GPIO.OUT) GPIO.output (9, False) GPIO.output(10,False) GPIO.output (11, False) GPIO.cleanup() sys.exit(0) signal.signal(signal.SIGINT,allLightsOff) While True: GPIO.output (9, True) time.sleep(3) GPIO. output (10, True) time.sleep(1) GPIO.output (9, False) GPIO. output (9, True) GPIO. output (11, True) time.sleep(5) GPIO. output (11, False) GPIO. output (10, True) time.sleep(2) GPIO. output (10, False)

Ln: 22 Col: 21