ASSIGNMENT-III

Qn:

LED BLINKING

```
import RPi.GPIO as GPIO
```

from time import sleep

GPIO.setwarnings(False)

GPIO.setmode(GPIO.BOARD)

GPIO.setup(8, GPIO.OUT, initial=GPIO.LOW)

while True: #infinite loop

GPIO.output(8, GPIO.HIGH) # Turn on

print("The LED is ON")

sleep(5) # Sleep for 5 second

GPIO.output(8, GPIO.LOW) # Turn off

print("The LED is OFF") sleep(5)