```
int t=2; int
e=3; void
setup()
Serial.begin(9600);
pinMode(t,OUTPUT);
pinMode(e,INPUT);
pinMode(12,OUTPUT);
}
void loop()
//ultrasonic sensor
digitalWrite(t,LOW);
digitalWrite(t,HIGH);
delayMicroseconds(10);
digitalWrite(t,LOW); float
dur=pulseIn(e,HIGH); float
dis=(dur*0.0343)/2;
Serial.print("Distance is: ");
Serial.println(dis);
//LED ON if(dis>=100)
{
digitalWrite(8,HIGH);
digitalWrite(7,HIGH);
}
//Buzzer For ultrasonic Sensor
if(dis>=100)
```

```
for(int i=0; i<=30000; i=i+10)
tone(12,i); delay(1000);
noTone(12);
delay(1000);
}
}
//Temperate Sensor double a=
analogRead(A0); double
t=(((a/1024)*5)-0.5)*100;
Serial.print("Temp Value: ");
Serial.println(t);
delay(1000);
//LED ON if(t>=100)
{
digitalWrite(8,HIGH);
digitalWrite(7,HIGH);
}
//Buzzer for Temperature Sensor
if(t>=100)
for(int i=0; i<=30000; i=i+10)
```

```
tone(12,i); delay(1000);
noTone(12);
delay(1000);
}

//LED OFF if(t<100)
{
digitalWrite(8,LOW);
digitalWrite(7,LOW);
}</pre>
```