SPRINT DELIVERY PLAN

Team ID	PNT2022TMID06438
Project Name	GAS LEAKAGE MONITORING AND ALERTING SYSTEM
Team Members	1 PURNACHANDRIGAA R 2 SELVANAYAKI M 3 VISHNUPRIYA S 4 KIRIRAJ S

- 1. Identify the Problem
- 2. Prepare an abstract and Problem Statement
- 3. List a required Objects needed
- 4. Create a code and run it
- 5. Test with a created code and check the designed Prototype
- 6. Solution for the problem is found