IBM Assingment-4

Write code and connections in wokwi for ultrasonic sensor.

Whenever distance is less than 100 cms send "alert" to ibm cloud and display in device recent events.

By:

NAME: S. Matheshwari

Reg No: 952319104029

```
Turn the LED on when an object is within 100cm range.

Copyright (C) 2021, Uri Shaked

*/

#define ECHO_PIN 2
#define TRIG_PIN 3

void setup() {
Serial.begin(115200);
pinMode(LED_BUILTIN, OUTPUT);
pinMode(TRIG_PIN, OUTPUT);
pinMode(ECHO_PIN, INPUT);
}

float readDistanceCM() {
digitalWrite(TRIG_PIN, LOW);
delayMicroseconds(2);
```

digitalWrite(TRIG PIN, HIGH);

digitalWrite(TRIG PIN, LOW);

return duration * 0.034 / 2;

duration = pulseIn(ECHO_PIN, HIGH);

float distance = readDistanceCM();

delayMicroseconds(10);


}

void
loop() {

CODING:

```
bool isNearby = distance < 100;
digitalWrite(LED_BUILTIN, isNearby);
   Serial.print("Measured distance: ");
   Serial.println(readDistanceCM());
   delay(100);
}</pre>
```

OUTPUT:



Link:

https://wokwi.com/projects/290056311044833800