## Assignment -1

Assignment Date	30 October 2022
Student Name	Athira V R
Student Roll Number	910019106007
Maximum Marks	2 Marks

## **Question:**

Write a code and connections in wokwi for the ultrasonic sensor. Whenever the distance is less than 100cms send an "Alert" to IBM cloud and display in the device recent events.

## Code:

```
int led = 8;
int trig = 2;
int echo = 5;
int buzzer = 4;
void setup()
  Serial.begin(9000);
  pinMode(led,OUTPUT);
  pinMode(trig,OUTPUT);
  pinMode(echo,INPUT);
  pinMode(buzzer,OUTPUT);
void loop()
  double a = analogRead(A2);
  double v = a / 1024;
  double tvolt = v * 5;
  double o = tvolt - 0.5;
  double t = 0 * 100;
  Serial.print("Temperature in degree");
  Serial.println(t);
  if(t >= 50)
```

```
digitalWrite(led,HIGH);
else
  digitalWrite(led,LOW);
digitalWrite(trig,LOW);
digitalWrite(trig,HIGH);
delayMicroseconds(10);
digitalWrite(trig,LOW);
float dur = pulseIn(echo,HIGH);
float dist = (dur * 0.343)/2;
Serial.print("Distance");
Serial.println(dist);
if(dist >= 17)
  digitalWrite(buzzer,HIGH);
else
  digitalWrite(buzzer,LOW);
```

## Output :

