# GAS LEAKAGE MONITORING&ALERTING SYSTEM FOR INDUSTRIES

#### IBM NALAIYATHIRAN

## PROJECT DEVELOPMENT PHASE

### **SPRINT 4:**

TITLE	GAS LEAKAGE MONITORING&ALTERING SYSTEM FOR INDUSTRIES
DOMAIN NAME	INTERNET OF THINGS
TEAM ID	PNT2022TMID13097

## **PROGRAM:**

```
#include <LiquidCrystal.h>
LiquidCrystal lcd(5,6,8,9,10,11);
int redled = 2;
int greenled = 3;
int buzzer = 4;
int sensor = A0;
int sensorThresh = 400;
void setup()
pinMode(redled, OUTPUT);
pinMode(greenled,OUTPUT);
pinMode(buzzer,OUTPUT);
pinMode(sensor,INPUT);
Serial.begin(9600); lcd.begin(16,2);
void loop() {
int analogValue = analogRead(sensor);
Serial.print(analogValue);
if(analogValue>sensorThresh)
digitalWrite(redled,HIGH);
digitalWrite(greenled,LOW);
tone(buzzer, 1000, 10000);
lcd.clear(); lcd.setCursor(0,1);
lcd.print("ALERT");
delay(1000);
lcd.clear();
lcd.setCursor(0,1);
lcd.print("EVACUATE");
delay(1000);
}
else
digitalWrite(greenled,HIGH);
digitalWrite(redled,LOW);
noTone(buzzer);
```

```
lcd.clear();
lcd.setCursor(0,0);
lcd.print("SAFE");
delay(1000); lcd.clear();
lcd.setCursor(0,1);
lcd.print("ALL CLEAR");
delay(1000);
}
```