Assignment -4

Assignment Date	19 October 2022
Student Name	DHIVYA S
Student Roll Number	620319104006
Maximum Marks	2 Marks

Question:

Write code and connections in wokwi for the ultrasonic sensor. Whenever the distance is less than 100 cms send an "alert" to the IBM cloud and display in the device recent events. Upload document with wokwi share link and images of IBM cloud.


Solution:

```
//Pins
const int TRIG_PIN = 7;
const int ECHO_PIN =8;
//Anything over 400 cm (23200 us pulse) is "out of range"
const unsigned int MAX_DIST = 23200;
void setup() {
// The Trigger pin will tell the sensor to range findPin
Mode(TRIG_PIN, OUTPUT);
digital Write(TRIG_PIN, LOW);
//Set Echo pin as input to measure the duration of
//pulses coming back from the distance sensor
pinMode(ECHO_PIN, INPUT );
// We'll use the serial monitor to view the sensor output
 Serial.begin(9600);
 }
```

```
void loop() {
unsigned long t1;
unsigned long t2;
unsigned long pulse_width;
float cm;
float inches;
// Hold the trigger pin high for at least 10 us
digitalWrite(TRIG_PIN, HIGH);
delayMicroseconds(10);
digitalWrite(TRIG_PIN, LOW);
// Wait for pulse on echo pin
while (digitalRead( ECHO_PIN )==0 );
// Measure how long the echo pin was held high (pulse width)
// Note: the micros() counter will overflow after-70 min
t1 = micros();
while (digitalRead(ECHO_PIN) ==1);
t2 = micros();
pulse\_width = t2-t1;
// Calculate distance in centimeters and inches. The constants
//are found in the datasheet, and calculated from the assumed speed
// of sound in air at sea level (- 340m/s)
cm=pulse_Width / 58;
inches = pulse_width/148.0;
// Print out results
if (pulse_width >MAX_DIST)
{
```

Output:

1. If the distance is less than $100 \ \mathrm{cms}$, it alerts.



2. If the distance is more than 100 cms, it won't alert

```
WOKWÎ ■ SAVE - SHARE
                                                                                                                                                                        Docs A
              diagram json ● Library Manager ▼
                                                                                                                                                                  Ō00:00.599 (%62%
         const int TRIG_PIN = 7;
     3 const int ECHO_PIN = 8;
     5 // Anything over 400 cm (23200 us pulse) is "out of range"
6 const unsigned int MAX_DIST = 23200;
     8 void setup() {
           // The Trigger pin will tell the sensor to range find
           pinHode(TRIG_PIN, OUTPUT);
digitalWrite(TRIG_PIN, LOW);
                                                                                                                   SETTITE DISTRAC (PAR -) ES
    11
                                                                                                                    :OO UNO ...
           //Set Echo pin as input to measure the duration of
//pulses coming back from the distance sensor
    14
           pinMode(ECHO_PIN, INPUT);
           // We'll use the serial monitor to view the sensor output
    19
           Serial.begin(9600);
                                                                                                                       POWER ANALOG IN
    20 }
    22 void loop() {
    23
           unsigned long t1;
           unsigned long t2;
unsigned long pulse_width;
                                                                                           The Measured Distance in cm : 227.10
                                                                                           ********************
                                                                                                                                              Activate Windows
          float inches;
                                                                                                                                              Go to Settings to activate Windows.
```

3. Simulation and code execution

