## **Prerequisites**

## **Python Software**

Date	09 November 2022
Team ID	PNT2022TMID06322
Project Name	Project – Smart Farmer - IOT Enabled
	Smart Farming Application

## Python 3.7.4 latest version was installed

```
Code.py - C:/Users/ARUN/Desktop/Code.py (3.7.0)
File Edit Format Run Options Window Help
import random
                                                                Python 3.7.0 (v3.7.0:1bf9cc5093, Jun 27 2018, 04:5
                                                                9:51) [MSC v.1914 64 bit (AMD64)] on win32
Type "copyright", "credits" or "license()" for mor
while (True):
    o=random.randint(10,99)
    p=random.randint(10,99)
                                                                e information.
    if(o > 30 and p > 75):
  print("High Temprature and Humidity of:",o,p,
elif(o < 35 and p < 65):
    print("Normal Temprature and Humidity of:</pre>
                                                                >>>
                                                                           ====== RESTART: C:/Users/ARUN/Desktop
                                                                /Code.py =====
                                                                High Temprature and Humidity of: 44 78 % alarm is
           break
                                                                High Temprature and Humidity of: 66 89 % alarm is
                                                                High Temprature and Humidity of: 71 92 % alarm is
                                                                High Temprature and Humidity of: 35 80 % alarm is
                                                                High Temprature and Humidity of: 75 96 % alarm is
                                                                High Temprature and Humidity of: 91 95 % alarm is
                                                                High Temprature and Humidity of: 85 80 % alarm is
                                                                High Temprature and Humidity of: 54 88 % alarm is
                                                                High Temprature and Humidity of: 92 84 % alarm is
                                                                on
                                                                Normal Temprature and Humidity of: 14 53 % alarm i
                                                                s off
                                                                >>>
```