## SMART FARMER – IoT ENABLED SMART FARMER APPLICATION ASSIGNMENT – 4


Team ID	PNT2022TMID03620
Name	KRITHIKA R
Roll No.	212219060146

1. Write Code and connections in wokwi for ultrasonic sensor. Whenever distance is less than 100 centimetres send an 'alert' to the ibm cloud and display in device recent events.

## **Program:**


```
#define ECHO_PIN 2
#define TRIG_PIN 3
void setup() {
Serial.begin(115200);
pinMode(LED_BUILTIN, OUTPUT);
pinMode(TRIG_PIN, OUTPUT);
pinMode(ECHO_PIN, INPUT);
}
float readDistanceCM() {
digitalWrite(TRIG_PIN, LOW);
delayMicroseconds(2);
digitalWrite(TRIG_PIN, HIGH);
delayMicroseconds(10);
digitalWrite(TRIG_PIN, LOW);
int duration = pulseIn(ECHO_PIN, HIGH);
return duration * 0.034 / 2;
}
void loop() {
float distance = readDistanceCM();
if(distance<100)
 Serial.println("Alert!!!!!!");
 Serial.print("Measured distance: ");
 Serial.println(readDistanceCM());
delay(100);
```

## Wokwi Editor window:



## **Results:**

1. The measured distance is less than 100 centimetres, it gives alert message



2. The measured distance is more than 100 centimetres, it will not give alert message

