Assignment -4

Assignment Date	26 October 2022
Student Name	Akshaya S
Team ID	PNT2022TMID18250
Project Name	Gas Leakage Monitoring & Alerting
	System For Industries
Maximum Marks	2 Marks

Write code and connections in wokwi for the ultrasonic sensor. Whenever the distance is less than 100 cms send an "alert" to the IBM cloud and display in the device recent events.

```
#define ECHO_PIN 2
#define TRIG_PIN 3
#define organization = "mmbh4c"
#define deviceType = "Ultrasonic"
#define deviceId = "pga460_sensor"
#define authMethod = "use-token-auth"
#define authToken = "123456789"
void setup() {
Serial.begin(9600);
pinMode(TRIG_PIN, OUTPUT);
pinMode(ECHO_PIN, INPUT);
float readDistanceCM() {
digitalWrite(TRIG_PIN, LOW);
delayMicroseconds(2);
digitalWrite(TRIG_PIN, HIGH);
delayMicroseconds(10);
digitalWrite(TRIG_PIN, LOW);
int duration = pulseIn(ECHO_PIN, HIGH);
return duration * 0.034 / 2;
}
```

```
void loop() {
float distance = readDistanceCM();
if(distance <= 100)
{
   Serial.println("person detected ");
}
else{
   Serial.print("Measured distance: ");
   Serial.println(readDistanceCM());
}
delay(1000);
}</pre>
```

