

```
int val = 0;
int sensor = 0;
void setup()
{
 pinMode(A0, INPUT);
 pinMode(6, OUTPUT);
 Serial.begin(9600);
}
void loop()
 sensor = analogRead(A0);
 val = sensor;
if (sensor >= 930) {
  analogWrite(6, val);
Serial.println(sensor);
 } else {
  analogWrite(6, LOW);
  Serial.println(sensor);
}
 delay(10);
}
```