SPRINT 4

PNT2022TMID11003

```
#include
<OneWire.h>
              #include <DallasTemperature.h>
              #define ONE WIRE BUS 5
              OneWire oneWire(ONE WIRE BUS);
              DallasTemperature sensors(&oneWire);
              float Celcius=0;
              float Fahrenheit=0;
              float voltage=0;
              const int analogInPin = A0;
              int sensorValue = 0;
              unsigned long int avgValue;
              float b;
              int buf[10],temp;
              void setup(void)
              {
               Serial.begin(9600);
               sensors.begin();
               int sensorValue = analogRead(A1);
               voltage = sensorValue * (5.0 / 1024.0);
              }
              void loop(void)
               sensors.requestTemperatures();
               Celcius=sensors.getTempCByIndex(0);
               Fahrenheit=sensors.toFahrenheit(Celcius);
               for(int i=0;i<10;i++)</pre>
               buf[i]=analogRead(analogInPin);
               delay(10);
              }
              for(int i=0;i<9;i++)</pre>
               for(int j=i+1;j<10;j++)</pre>
               if(buf[i]>buf[j])
               {
```

```
temp=buf[i];
buf[i]=buf[j];
buf[j]=temp;
}
 }
}
for(int i=2;i<8;i++)</pre>
avgValue+=buf[i];
float pHVol=(float)avgValue*5.0/1024/6;
float phValue = -5.70 * pHVol + 21.34;
Serial.println(phValue);
Serial.print("pH");
Serial.print(" C ");
Serial.print(Celcius);
Serial.print(voltage);
Serial.print("V");
delay(10000);
}
```