```
int t=2;
int e=3;
void setup()
Serial.begin(9600);
pinMode(t,OUTPUT);
pinMode(e,INPUT);
pinMode(12,OUTPUT
);
void loop()
{
//ultrasonic sensor
digitalWrite(t,LOW);
digitalWrite(t,HIGH);
delayMicroseconds(10);
digitalWrite(t,LOW);
float dur=pulseIn(e,HIGH);
float dis=(dur*0.0343)/2;
Serial.print("Distance is:
");Serial.println(dis);
 //LED ON
if(dis > = 100)
  digitalWrite(8,HIGH
  digitalWrite(7,HIGH
  );
```

```
//Buzzer For ultrasonic Sensor
if(dis > = 100)
for(int i=0; i<=30000; i=i+10)
tone(12,i);
delay(1000);
noTone(12);
delay(1000);
}
}
//Temperate Sensor
double a=
analogRead(A0);
double t=(((a/1024)*5)-0.5)*100;
Serial.print("Temp Value: ");
Serial.println(t);
delay(1000);
//LED
ON
if(t>=100
)
 digitalWrite(8,HIGH
 );
 digitalWrite(7,HIGH
 );}
```

```
//Buzzer for Temperature Sensor
if(t>=100)
{
for(int i=0; i<=30000; i=i+10)
{
tone(12,i);
delay(1000);
noTone(12);
delay(1000);
}

//LED OFF
if(t<100)
{
digitalWrite(8,LOW);
digitalWrite(7,LOW);
}
```