# GAS LEAKAGE MONITORING ALERTING SYSTEM FOR INDUSTRIES

TITLE	GAS LEAKAGE MONITORING ALERTING SYSTEM FOR INDUSTRIES
DOMAIN NAME	INTERNET OF THINGS
TEAM ID	PNT2022TMID05241
TEAM MEMBERS	MAHALAKSHMI.G NAAGALAKSHMI.S NISHANTHKARTHICK.G PREETHI.T

CREATE AND CONFIGURE IBM SERVICES IOT WATSON PLATFORM

STEP 1: LOG IN TO CLOUD

STEP 2: CLICK CATALOG WHERE YOU FIND THE SERVICES AND THE INTERNET OFTHING YOU CAN SELECT AND MAKE LOCATION AS LONDON

STEP 3: CLICK CREATE AND THE LAUNCH TAB GET OPEN THEN CLICK LAUNCH

STEP 4: IT REDIRECTS YOU TO IBM WATSON PLATFORM WHERE YOU NEED TO CLICK SIGN IN

STEP 6: WHERE YOU FIND THIS TAB WHICH IS USED TO ADD DEVICE, APP, MEMBER, USAGE AND SECURITY CAN BE WORKED

STEP 7: CHECK BOARDS FOR RISK AND SECURITY OVERVIEW CARD, IT USES FOR GRAPHICAL REPRESENTATION BOARDS

STEP 8: AFTER CLICKING CREATE A NEW DEVICE/ADD DEVICE YOU CAN CHOOSE A DEVICE TYPE AND DEVICE ID AND COMPLETE THE FOLLOWING INFORMATION TO CREATE A DEVICE

STEP 9: CREATED A DEVICE OF NODEMCU

Device Drilldown - 19998

Device Credentials

Device Credentials

You registered your device to the organization. Add these credentials to the device to connect it to the platform. After the device is connected, you can navigate to view connection and event details.

Organization ID	ty7hvb
Device Type	NodeMCU
Device ID	19998
Authentication Method	use-token-auth
Authentication Token	19998226

⚠ Authentication tokens are non-recoverable. If you misplace this token, you will need to re-register the device to generate a new authentication token.