Assignment 4

Objective:

To develop a code and make connections in wokwi for ultrasonic sensor, whenever distance is less than 100 cm send "Alert" to IBM cloud and display in device recent events.

Code:

```
const int TRIG_PIN = 7;
const int ECHO_PIN = 8;

const unsigned int MAX_DIST = 23600;
void setup() {

pinMode(TRIG_PIN, OUTPUT);
digitalWrite(TRIG_PIN, LOW);

pinMode(ECHO_PIN, INPUT);

Serial.begin(9600);
}
void loop() {

unsigned long t1;
unsigned long t2;
unsigned long pulse_width;
float cm;
float inches;

digitalWrite(TRIG_PIN, HIGH);
delayMicroseconds(10);
```

```
digitalWrite(TRIG_PIN, HIGH);
delayMicroseconds(10);
digitalWrite(TRIG_PIN, LOW);

while (digitalRead(ECHO_PIN) == 0);

t1 = micros();
while (digitalRead(ECHO_PIN) == 1);
t2 = micros();
pulse_width = t2 - t1;

cm = pulse_width / 58;
inches = pulse_width / 148.0;

if (pulse_width > MAX_DIST) {

Serial.printlr("Out of range");
}
else
{

Serial.print("The Measured Distance in cm: "); Serial.printlr(cm);
```

Stimulation:

