PYTHON CODE

Date	14 NOVEMBER 2022
Team ID	PNT2022TMID14284
Project Name	GAS LEAKAGE MONITORING AND ALERTING SYSTEM FOR INDUSTRIES

Code:

```
import random
print('Hazardous gas Level=',str(random.randint(0,100)))
print('Temperature=',str(random.randint(0,100)))
print('Humidity=',str(random.randint(0,100)))
print('Pressure=',str(random.randint(0,100)))
```

```
pythoncde.py - C:/Users/kotur/AppData/Local/Programs/Python/Python311/pythoncde.py (3.11.0)
File Edit Format Run Options Window Help
import random
print('Hazardous gas Level=',str(random.randint(0,100)))
print('Temperature=',str(random.randint(0,100)))
print('Humidity=',str(random.randint(0,100)))
print('Pressure=',str(random.randint(0,100)))
```

Output:

```
File Edit Shell Debug Options Window Help

Python 3.11.0 (main, Oct 24 2022, 18:26:48) [MSC v.1933 64 bit (AMD64)] on win32 Type "help", "copyright", "credits" or "license()" for more information.

= RESTART: C:/Users/kotur/AppData/Local/Programs/Python/Python311/pythoncde.py = Hazardous gas Level= 4 Temperature= 45 Humidity= 26 Pressure= 50

>>>
```

