

Doc Number : ICP-DOC-INTOUCH

Revision : 0

Last Modified: 23-Jan-2024

WONDERWARE INTOUCH SUPPORTING DOCUMENT

COPY RIGHT

All rights reserved by ICPro Solutions Pvt. Ltd. Reproduction or issue is not permitted without the written permission of ICPro Solutions Pvt. Ltd



Doc Number : ICP-DOC-INTOUCH

Revision : 0

Last Modified: 23-Jan-2024

Duning Manage		

Project Name:

INTOUCH SUPPORTING DOCUMENT

End Customer Name:

N/A

Document No:

ICP-DOC-INTOUCH

Document Title:

WONDERWARE INTOUCH APPLICATION MANUAL FOR TREND HISTORY

Prepared by:

ICPro Solutions Pvt. Ltd.

REVISION HISTORY

<u>-</u>					
Initial Release for Review	00	23-01-2024	PK		
REVISION DETAILS	REVISION	REV. DATE	PREP. BY	CHECKED	APPROVED



Doc Number : ICP-DOC-INTOUCH

Revision : 0

Last Modified: 23-Jan-2024

Contents

1.	Intro	oduction	4
	1.1	Purpose	4
2.	НМІ	I Application Management	4
	2.1	Trends Configuration	4



Doc Number : ICP-DOC-INTOUCH

Revision : 0

Last Modified: 23-Jan-2024

1. Introduction

1.1 Purpose

The objective of this document is to explain clear instructions for the Wonderware Intouch application project to creating and configuring the trends tags and configuration steps for Trend History. These topics are explained.


2. HMI Application Management

2.1 Trends Configuration


HMI application backup Trends tag creation and trend configuration are showing below:

Step 1: Need to create some tags for Trends screen:

1. HistTrend: Hist Trend Type.



2. His trend tags for Pan Minimum in trend screen: Memory Integer Type.






Doc Number : ICP-DOC-INTOUCH


Revision : 0

Last Modified: 23-Jan-2024

3. His trend tags for Pen scale in trend screen: Memory Integer Type.



4. From Symbol factory copy and paste the historical trend, in the properties give the created History tag.







Doc Number : ICP-DOC-INTOUCH

Revision : 0

Last Modified: 23-Jan-2024



5. Once check the runtime for Trend History and starting the screen will be empty,



6. For History trend we need to start the application:

Hisdata (Application)

Path: Local Disk (c) > Program files (x86) > Wonderware > Intouch > Hisdata




Double click to start the application, it will be placed in task bar,



Doc Number : ICP-DOC-INTOUCH


Revision : 0

Last Modified: 23-Jan-2024



7. Historical trend is required for the project, first need to configure the path for History trend.

Special > Configure > Historical Logging



In Historical logging popup will open,



In this above popup need to enabling the Logging under the path we given, now we create the folder in C\: History

In popup also the log files period needs to mention as per our requirements.

- 8. After completing these configurations go to the runtime for History Trend,
- 9. In Trend History screen: Double click to assign the tag for Pen 1 with, respective color,
- 10. In starting time, the trend history will be empty after some time trend will logging under our configuration path,




Doc Number : ICP-DOC-INTOUCH

Revision : 0

Last Modified: 23-Jan-2024

11. In Trend screen: Double click for configuring the new tag for Trend,



12. After some time, the trend will be log and that popup, we can able to type the required date/time for Historical trend with respective tags using the cursor.





Doc Number : ICP-DOC-INTOUCH

Revision : 0

Last Modified: 23-Jan-2024

13. Once entering the Time and date, for the respective tag and we can able to see that the Trend history (Process value for the tag).

