OOO X AAOmega Spectrograph Control			
AAOmega Spectrograph control dialog (Ctrl-S)			
Available			
Instrument Health Overall Instrument Health			
click value for details		OK	
Room Door		CLOSED	
Slit Exchange			
Observation S	lit.	IFU	
Slit Clam	ps	ALL_CLOSED	
Back illumination u	nit	Retracted	
Clam Sh		OPEN	
Spectrograph Light Path			
Shutt	ter		
Hartmann Shutter	'S	0	
Dichroic Nar	ne	X5700	
Dark Slid		0	0
VPH Properties = = = = =			
Set VPH Positions			
	m	Blue	Red
VPH	-	580V	1700D
VPH ruli		581	1700
VPH and	5	36.13	35.67
Camera and		32.30	31.80
Central Waveleng		8999 20635	3033 6894
Blaze Wavelength dispersion		1.043	0.356
ord		1.043	1.336
Camera Focus			
Spatial 1		3000	1000
Spectral T	iit	2000	1555
Foc	us	1000	4000
Auto Focus - Contrast			
Focus Mechanisum Control			
Calibrate AAOmega Blue Arm (Old Style)			
Calibrate AAOmega Red Arm (Old Style)			
Warning Reason (max 6 lines) No AAOmega warnings at this time.			