

1 Dies you have
a die folder holding layout, pins, contract and build record
Dies you do not have yet
a frame spec
chiplet-die-flow
pad-frame
2 The system file
system.chiplet
holding carrier, dies, links, rails and external pads
3 validate
packaging-flow validate
4 place
packaging-flow place
5 run
packaging-flow run
6
die U1, die U2 (accept)
resume
interposer (sign)
resume
assembly (sign)
resume
external interface (sign)
7 verdict
packaging-flow map
packaging-flow verify