

Instructions

Write a programme using linear and circular interpolation with centre line programming to machine the component shown


Input the part programme in the simulation package and simulate the tool movements

Dry run the programme on the CNC machine with a Z axis shift

Deburr the component

Clean the machine after use

Standards



Time 2 hours