

Module 7: Unit 2

Exercise No.2.7.2c

Instructions

Under instructor supervision

Write a programme using linear and circular interpolation with centre line programming to machine the component shown

Input the part programme in the simulation package and simulate the tool movements

Input the part programme in the CNC machine


Dry run the programme on the CNC machine with a Z axis shift

Machine the component and remove from vice

Deburr the component

Check the machined component for dimensional accuracy

Clean the machine after use



Standards Circuit functions to specifications

Time 2 hours