AACRAID Driver for Linux (take two)

Introduction

The aacraid driver adds support for Adaptec (http://www.adaptec.com) RAID controllers. This is a major rewrite from the original Adaptec supplied driver. It has significantly cleaned up both the code and the running binary size (the module is less than half the size of the original).

Supported Cards/Chipsets

PCI ID (pci.ids)	OEM	Product
9005:0285:9005:0285	Adaptec	2200S (Vulcan)
9005:0285:9005:0286	Adaptec	2120S (Crusader)
9005:0285:9005:0287	Adaptec	
9005:0285:9005:0288	Adaptec	· · ·
9005:0285:9005:0289		3240S (Tornado)
9005:0285:9005:028a		2020ZCR (Skyhawk)
9005:0285:9005:028b	Adaptec	, · · /
9005:0286:9005:028c	Adaptec	,
9005:0286:9005:028c	Adaptec	
9005:0286:9005:028d		2130S (Lancer)
9005:0285:9005:028e	-	2020SA (Skyhawk)
9005:0285:9005:028f		2025SA (Terminator)
9005:0285:9005:0290		2410SA (Jaguar)
9005:0285:103c:3227		2610SA (Bearcat HP release)
9005:0285:9005:0293		21610SA (Corsair-16)
9005:0285:9005:0296		2240S (SabreExpress)
9005:0285:9005:0292	Adaptec	` /
9005:0285:9005:0297	Adaptec	,
9005:0285:9005:0298	Adaptec	
9005:0285:9005:0298	Adaptec	,
9005:0285:9005:0299 9005:0285:9005:029a	Adaptec	/
9005:0286:9005:029b	Adaptec	,
9005:0286:9005:029c	Adaptec	,
9005:0286:9005:029d		2420SA (Intruder HP release)
9005:0286:9005:02ac		1800 (Typhoon44)
9005:0285:9005:02b5	Adaptec	,
9005:0285:15d9:02b5	SMC	AOC-USAS-S4i
9005:0285:9005:02b6	Adaptec	· ·
9005:0285:15d9:02b6	SMC	AOC-USAS-S8i
9005:0285:9005:02b7	Adaptec	
9005:0285:9005:02bb	Adaptec	` '
9005:0285:9005:02bc	Adaptec	3805 (Marauder80LP)
9005:0285:9005:02c7	Adaptec	3085 (Marauder08ELP)
9005:0285:9005:02bd	Adaptec	
9005:0285:9005:02be	Adaptec	· · ·
9005:0285:9005:02c3	Adaptec	51205 (Voodoo120)
9005:0285:9005:02c4	Adaptec	
9005:0285:15d9:02c9	SMC	AOC-USAS-S4iR
9005:0285:15d9:02ca	SMC	AOC-USAS-S8iR
9005:0285:9005:02ce	Adaptec	
9005:0285:9005:02cf	Adaptec	
9005:0285:9005:02d0	Adaptec	52445 (Voodoo244)
9005:0285:9005:02d1	Adaptec	5405 (Voodoo40)
9005:0285:15d9:02d2	SMC	AOC-USAS-S8i-LP
9005:0285:15d9:02d3	SMC	AOC-USAS-S8iR-LP
9005:0285:9005:02d4	Adaptec	ASR-2045 (Voodoo04 Lite)
9005:0285:9005:02d5	Adaptec	ASR-2405 (Voodoo40 Lite)
9005:0285:9005:02d6	Adaptec	ASR-2445 (Voodoo44 Lite)

PCI ID (pci.ids)	OEM	Product
9005:0285:9005:02d7	Adaptec	ASR-2805 (Voodoo80 Lite)
9005:0285:9005:02d8	Adaptec	
9005:0285:9005:02d9	Adaptec	,
9005:0285:9005:02da	Adaptec	` '
1011:0046:9005:0364	Adaptec	,
1011:0046:9005:0365	Adaptec	<u> </u>
9005:0287:9005:0800		Themisto (Jupiter)
9005:0200:9005:0200	Adaptec	
9005:0286:9005:0800	Adaptec	
1011:0046:9005:1364	Dell	PERC 2/QC (Quad Channel, Mustang)
1011:0046:9005:1365	Dell	PERC 2/QC (Quad Channel, Mustang)
1028:0001:1028:0001	Dell	PERC 2/Si (Iguana)
1028:0003:1028:0003	Dell	PERC 3/Si (SlimFast)
1028:0003:1028:0003	Dell	PERC 3/Di (Opal)
1028:0002:1028:0002	Dell	PERC 3/SiF (Iguana)
1028:0004:1028:00d0	Dell	PERC 3/Dif (Iguana)
1028:0004:1028:00d0 1028:0002:1028:00d1	Dell	PERC 3/Div (Viper)
		PERC 3/DiV (viper)
1028:0002:1028:00d9	Dell	I LANC JIDIL (LEAUS)
1028:000a:1028:0106	Dell	PERC 3/DiJ (Jaguar)
1028:000a:1028:011b	Dell	PERC 3/DiD (Dagger)
1028:000a:1028:0121	Dell	PERC 3/DiB (Boxster)
9005:0285:1028:0287	Dell	PERC 320/DC (Vulcan)
9005:0285:1028:0291	Dell	CERC 2 (DellCorsair)
1011:0046:103c:10c2	HP	NetRAID-4M (Mustang)
9005:0285:17aa:0286	Legend	S220 (Crusader)
9005:0285:17aa:0287	Legend	S230 (Vulcan)
9005:0285:9005:0290	IBM	ServeRAID 7t (Jaguar)
9005:0285:1014:02F2	IBM	ServeRAID 8i (AvonPark)
9005:0286:1014:9540	IBM	ServeRAID 8k/8k-14 (AuroraLite)
9005:0286:1014:9580	IBM	ServeRAID 8k/8k-l8 (Aurora)
9005:0285:1014:034d	IBM	ServeRAID 8s (Marauder-E)
9005:0286:9005:029e	ICP	ICP9024RO (Lancer)
9005:0286:9005:029f	ICP	ICP9014RO (Lancer)
9005:0286:9005:02a0	ICP	ICP9047MA (Lancer)
9005:0286:9005:02a1	ICP	ICP9087MA (Lancer)
9005:0285:9005:02a4	ICP	ICP9085LI (Marauder-X)
9005:0285:9005:02a5	ICP	ICP5085BR (Marauder-E)
9005:0286:9005:02a6	ICP	ICP9067MA (Intruder-6)
9005:0285:9005:02b2	ICP	(Voodoo 8 internal 8 external)
9005:0285:9005:0268	ICP	ICP5445SL (Voodoo44)
9005:0285:9005:02b9	ICP	ICP5085SL (Voodoo80)
9005:0285:9005:02ba	ICP	ICP5805SL (Voodoo08)
9005:0285:9005:02bf	ICP	ICP5045BL (Marauder40LP)
9005:0285:9005:02c0	ICP	ICP5085BL (Marauder80LP)
9005:0285:9005:02c8	ICP	ICP5805BL (Marauder08ELP)
9005:0285:9005:02c1	ICP	ICP5125BR (Marauder120)
9005:0285:9005:02c2	ICP	ICP5165BR (Marauder160)
9005:0285:9005:02c5	ICP	ICP5125SL (Voodoo120)
9005:0285:9005:02c6	ICP	ICP5165SL (Voodoo160)
9005:0286:9005:02ab		(Typhoon40)
9005:0286:9005:02ad		(Aurora ARK)
9005:0286:9005:02ae		(Aurora Lite ARK)
9005:0285:9005:02b0		(Sunrise Lake ARK)
9005:0285:9005:02b1	Adaptec	,
9005:0285:108e:7aac	SUN	STK RAID REM (Voodoo44 Coyote)
9005:0285:108e:/aac 9005:0285:108e:0286	SUN	STK RAID REW (Voodoo44 Coyote) STK RAID INT (Cougar)
9005:0285:108e:0286 9005:0285:108e:0287	SUN	STK RAID INT (Cougar) STK RAID EXT (Prometheus)
9005:0285:108e:7aae	SUN	STK RAID EAT (Fronteurus) STK RAID EM (Narvi)
7003.0203.100e./aae	BUIN	STE VAID EM (MINI)

People

Alan Cox <alan@lxorguk.ukuu.org.uk>

Christoph Hellwig < hch@infradead.org>

• updates for new-style PCI probing and SCSI host registration, small cleanups/fixes

Matt Domsch < matt domsch@dell.com>

• revision ioctl, adapter messages

Deanna Bonds

- non-DASD support, PAE fibs and 64 bit, added new adaptec controllers added new ioctls, changed scsi interface to use new error handler, increased the number of fibs and outstanding commands to a container
- fixed 64bit and 64G memory model, changed confusing naming convention where fibs that go to the hardware are consistently called hw_fibs and not just fibs like the name of the driver tracking structure

Mark Salyzyn@adaptec.com>

- Fixed panic issues and added some new product ids for upcoming hbas.
- Performance tuning, card failover and bug mitigations.

Achim Leubner < Achim Leubner @adaptec.com>

Original Driver

Adaptec Unix OEM Product Group

Mailing List

linux-scsi@vger.kernel.org (Interested parties troll here) Also note this is very different to Brian's original driver so don't expect him to support it.

Adaptec does support this driver. Contact Adaptec tech support or aacraid@adaptec.com

Original by Brian Boerner February 2001

Rewritten by Alan Cox, November 2001