Adaptec Aic7xxx Fast -> Ultra160 Family Manager Set v7.0

README for The Linux Operating System

The following information is available in this file:

- 1. Supported Hardware
- 2. Version History
- 3. Command Line Options
- 4. Contacting Adaptec

1. Supported Hardware

The following Adaptec SCSI Chips and Host Adapters are supported by the aic7xxx driver.

Chip	MIPS	Host Bus	MaxSync	MaxWidth	SCBs	Notes
aic7770	10	EISA/VL	10MHz	16Bit	4	1
aic7850	10	PCI/32	10MHz	8Bit	3	
aic7855	10	PCI/32	10MHz	8Bit	3	
aic7856	10	PCI/32	10MHz	8Bit	3	
aic7859	10	PCI/32	20MHz	8Bit	3	
aic7860	10	PCI/32	20MHz	8Bit	3	
aic7870	10	PCI/32	10MHz	16Bit	16	
aic7880	10	PCI/32	20MHz	16Bit	16	
aic7890	20	PCI/32	40MHz	16Bit	16	3 4 5 6 7 8
aic7891	20	PCI/64	40MHz	16Bit	16	3 4 5 6 7 8
aic7892	20	PCI/64-66	80MHz	16Bit	16	3 4 5 6 7 8
aic7895	15	PCI/32	20MHz	16Bit	16	2345
aic7895C	15	PCI/32	20MHz	16Bit	16	23458
aic7896	20	PCI/32	40MHz	16Bit	16	2345678
aic7897	20	PCI/64	40MHz	16Bit	16	2345678
aic7899	20	PCI/64-66	80MHz	16Bit	16	2345678

- 1. Multiplexed Twin Channel Device One controller servicing two busses.
- 2. Multi-function Twin Channel Device Two controllers on one chip.
- 3. Command Channel Secondary DMA Engine Allows scatter gather list and SCB prefetch.
- 4. 64 Byte SCB Support Allows disconnected, untagged request table for all possible target/lun combinations.
- 5. Block Move Instruction Support Doubles the speed of certain sequencer operations.
- 6. 'Bayonet' style Scatter Gather Engine Improves S/G prefetch performance.
- 7. Queuing Registers Allows queuing of new transactions without pausing the sequencer.
- 8. Multiple Target IDs Allows the controller to respond to selection as a target on multiple SCSI IDs.

Controller	Chip	Host-Bus	Int-Connectors	Ext-Connectors	Notes
AHA-274X[A]	aic7770	EISA	SE-50M	SE-HD50F	
AHA-274X[A]W	aic7770	EISA	SE-HD68F SE-50M	SE-HD68F	
AHA-274X[A]T	aic7770	EISA	2 X SE-50M	SE-HD50F	
AHA-2842	aic7770	VL	SE-50M	SE-HD50F	
AHA-2940AU	aic7860	PCI/32	SE-50M	SE-HD50F	
AVA-2902I	aic7860	PCI/32	SE-50M		
AVA-2902E	aic7860	PCI/32	SE-50M		
AVA-2906	aic7856	PCI/32	SE-50M	SE-DB25F	
APC-7850	aic7850	PCI/32	SE-50M		1
AVA-2940	aic7860	PCI/32	SE-50M		
AHA-2920B	aic7860	PCI/32	SE-50M		
AHA-2930B	aic7860	PCI/32	SE-50M		
AHA-2920C	aic7856	PCI/32	SE-50M	SE-HD50F	
AHA-2930C	aic7860	PCI/32	SE-50M		
AHA-2930C	aic7860	PCI/32	SE-50M		
AHA-2910C	aic7860	PCI/32	SE-50M		
AHA-2915C	aic7860	PCI/32	SE-50M		
AHA-2940AU/CN	aic7860	PCI/32	SE-50M	SE-HD50F	

Controller	Chip	Host-Bus	Int-Connectors	Ext-Connectors	Notes	
AHA-2944W	aic7870	PCI/32	HVD-HD68F HVD-	HVD-HD68F		
ALIA-29 11 W			50M	1110-110001		
AHA-3940W	aic7870	PCI/32	2 X SE-HD68F	SE-HD68F	2	
AHA-2940UW	aic7880	PCI/32	SE-HD68F SE-50M	SE-HD68F		
AHA-2940U	aic7880	PCI/32	SE-50M	SE-HD50F		
AHA-2940D	aic7880	PCI/32				
aHA-2940 A/T	aic7880	PCI/32				
AHA-2940D A/T	aic7880	PCI/32				
AHA-3940UW	aic7880	PCI/32	2 X SE-HD68F	SE-HD68F	3	
AHA-3940UWD	aic7880	PCI/32	2 X SE-HD68F	2 X SE-VHD68F	3	
AHA-3940U	aic7880	PCI/32	2 X SE-50M	SE-HD50F	3	
AHA-2944UW	aic7880	PCI/32	HVD-HD68F HVD- 50M	HVD-HD68F		
AHA-3944UWD	aic7880	PCI/32	2 X HVD-HD68F	2 X HVD-VHD68F	3	
AHA-4944UW	aic7880	PCI/32				
AHA-2930UW	aic7880	PCI/32				
AHA-2940UW Pro	aic7880	PCI/32	SE-HD68F SE-50M	SE-HD68F	4	
AHA-2940UW/CN	aic7880	PCI/32				
AHA-2940UDual	aic7895	PCI/32				
AHA-2940UWDual	aic7895	PCI/32				
AHA-3940UWD	aic7895	PCI/32				
AHA-3940AUW	aic7895	PCI/32				
AHA-3940AUWD	aic7895	PCI/32				
AHA-3940AU	aic7895	PCI/32				
AHA-3944AUWD	aic7895	PCI/32	2 X HVD-HD68F	2 X HVD-VHD68F		
AHA-2940U2B	aic7890	PCI/32	LVD-HD68F	LVD-HD68F		
AHA-2940U2 OEM	aic7891	PCI/64				
AHA-2940U2W	aic7890	PCI/32	LVD-HD68F SE- HD68F SE-50M	LVD-HD68F		
AHA-2950U2B	aic7891	PCI/64	LVD-HD68F	LVD-HD68F		
AHA-2930U2	aic7890	PCI/32	LVD-HD68F SE-50M	SE-HD50F		
AHA-3950U2B	aic7897	PCI/64				
AHA-3950U2D	aic7897	PCI/64				
AHA-29160	aic7892	PCI/64-66				
AHA-29160 CPQ	aic7892	PCI/64-66				
AHA-29160N	aic7892	PCI/32	LVD-HD68F SE-50M	SE-HD50F		
AHA-29160LP	aic7892	PCI/64-66				
AHA-19160	aic7892	PCI/64-66				
AHA-29150LP	aic7892	PCI/64-66				
AHA-29130LP	aic7892	PCI/64-66				
AHA-3960D	aic7899	PCI/64-66	2 X LVD-HD68F LVD-50M	2 X LVD-VHD68F		
AHA-3960D CPQ	aic7899	PCI/64-66	2 X LVD-HD68F LVD-50M	2 X LVD-VHD68F		
AHA-39160	aic7899	PCI/64-66	2 X LVD-HD68F LVD-50M	2 X LVD-VHD68F		

- 1. No BIOS support
- 2. DEC21050 PCI-PCI bridge with multiple controller chips on secondary bus
- 3. DEC2115X PCI-PCI bridge with multiple controller chips on secondary bus
- 4. All three SCSI connectors may be used simultaneously without SCSI "stub" effects.

2. Version History

- 7.0 (4th August, 2005)
 - Updated driver to use SCSI transport class infrastructure
 - Upported sequencer and core fixes from last adaptec released version of the driver.
- 6.2.36 (June 3rd, 2003)
 - o Correct code that disables PCI parity error checking.
 - Correct and simplify handling of the ignore wide residue message. The previous code would fail to report a residual if the transaction data length was even and we received an IWR message.
 - Add support for the 2.5.X EISA framework.

- Update for change in 2.5.X SCSI proc FS interface.
- · Correct Domain Validation command-line option parsing.
- When negotiation async via an 8bit WDTR message, send an SDTR with an offset of 0 to be sure the target knows we are async. This works around a firmware defect in the Quantum Atlas 10K.
- Clear PCI error state during driver attach so that we don't disable memory mapped I/O due to a stray write by some other driver probe that occurred before we claimed the controller.
- 6.2.35 (May 14th, 2003)
 - Fix a few GCC 3.3 compiler warnings.
 - o Correct operation on EISA Twin Channel controller.
 - Add support for 2.5.X's scsi_report_device_reset().
- 6.2.34 (May 5th, 2003)
 - Fix locking regression introduced in 6.2.29 that could cause a lock order reversal between the
 io_request_lock and our per-softc lock. This was only possible on RH9, SuSE, and kernel.org 2.4.X
 kernels.
- 6.2.33 (April 30th, 2003)
 - Dynamically disable PCI parity error reporting after 10 errors are reported to the user. These errors are
 the result of some other device issuing PCI transactions with bad parity. Once the user has been
 informed of the problem, continuing to report the errors just degrades our performance.
- 6.2.32 (March 28th, 2003)
 - Dynamically sized S/G lists to avoid SCSI malloc pool fragmentation and SCSI mid-layer deadlock.
- 6.2.28 (January 20th, 2003)
 - Domain Validation Fixes
 - Add ability to disable PCI parity error checking.
 - Enhanced Memory Mapped I/O probe
- 6.2.20 (November 7th, 2002)
 - · Added Domain Validation.

3. Command Line Options

Warning

ALTERING OR ADDING THESE DRIVER PARAMETERS INCORRECTLY CAN RENDER YOUR SYSTEM INOPERABLE. USE THEM WITH CAUTION.

Put a .conf file in the /etc/modprobe.d directory and add/edit a line containing options aic7xxx aic7xxx=[command[,command...]] where command is one or more of the following:

verbose

Definition: enable additional informative messages during driver operation.

Possible Values: This option is a flag

Default Value: disabled

debug:[value]

Definition:Enables various levels of debugging information**Possible Values:**0x0000 = no debugging, 0xffff = full debugging

Default Value: 0x0000

no_probe

probe_eisa_vl

Definition: Do not probe for EISA/VLB controllers. This is a toggle. If the driver is compiled to not probe

EISA/VLB controllers by default, specifying "no_probe" will enable this probing. If the driver is compiled to probe EISA/VLB controllers by default, specifying "no_probe" will disable this

probing.

Possible Values: This option is a toggle

Default Value: EISA/VLB probing is disabled by default.

pci_parity

Definition: Toggles the detection of PCI parity errors. On many motherboards with VIA chipsets, PCI

parity is not generated correctly on the PCI bus. It is impossible for the hardware to differentiate between these "spurious" parity errors and real parity errors. The symptom of this problem is a

stream of the message:

"scsi0: Data Parity Error Detected during address or write data phase"

output by the driver.

Possible Values: This option is a toggle

Default Value: PCI Parity Error reporting is disabled

no_reset

Definition: Do not reset the bus during the initial probe phase

Possible Values: This option is a flag

Default Value: disabled

extended

Definition: Force extended translation on the controller

Possible Values: This option is a flag

Default Value: disabled

periodic_otag

Definition: Send an ordered tag periodically to prevent tag starvation. Needed for some older devices

Possible Values: This option is a flag

Default Value: disabled

reverse_scan

Definition: Probe the scsi bus in reverse order, starting with target 15

Possible Values: This option is a flag

Default Value: disabled

global tag depth:[value]

Definition: Global tag depth for all targets on all busses. This option sets the default tag depth which may

be selectively overridden vi the tag_info option.

Possible Values: 1 - 253
Default Value: 32

tag_info:{{value[,value...]}[,{value[,value...]}...]}

Definition: Set the per-target tagged queue depth on a per controller basis. Both controllers and targets

may be omitted indicating that they should retain the default tag depth.

Possible Values: 1 - 253
Default Value: 32

Examples:

```
tag info:{{16,32,32,64,8,8,,32,32,32,32,32,32,32,32,32}}
```

On Controller 0:

- specifies a tag depth of 16 for target 0
- specifies a tag depth of 64 for target 3
- specifies a tag depth of 8 for targets 4 and 5
- leaves target 6 at the default
- specifies a tag depth of 32 for targets 1,2,7-15
- All other targets retain the default depth.

```
tag_info:{{},{32,,32}}
```

On Controller 1:

- specifies a tag depth of 32 for targets 0 and 2
- All other targets retain the default depth.

seltime:[value]

Definition: Specifies the selection timeout value

Possible Values: 0 = 256 ms, 1 = 128 ms, 2 = 64 ms, 3 = 32 ms

Default Value: 0

dv: {value[,value...]}

Definition: Set Domain Validation Policy on a per-controller basis. Controllers may be omitted indicating

that they should retain the default read streaming setting.

Possible Values: < 0 Use setting from serial EEPROM.

0 Disable DV
> 0 Enable DV

Default Value: SCSI-Select setting on controllers with a SCSI Select option for DV. Otherwise, on for

controllers supporting U160 speeds and off for all other controller types.

Example:

dv:{-1,0,,1,1,0}

- On Controller 0 leave DV at its default setting.
- On Controller 1 disable DV.
- Skip configuration on Controller 2.
- On Controllers 3 and 4 enable DV.
- On Controller 5 disable DV.

Example:

options aic7xxx aic7xxx=verbose,no_probe,tag_info:{{},{,,10}},seltime:1

enables verbose logging, Disable EISA/VLB probing, and set tag depth on Controller 1/Target 2 to 10 tags.

4. Adaptec Customer Support

A Technical Support Identification (TSID) Number is required for Adaptec technical support.

The 12-digit TSID can be found on the white barcode-type label included inside the box with your
product. The TSID helps us provide more efficient service by accurately identifying your product and
support status.

Support Options

- Search the Adaptec Support Knowledgebase (ASK) at http://ask.adaptec.com for articles, troubleshooting tips, and frequently asked questions about your product.
- For support via Email, submit your question to Adaptec's Technical Support Specialists at http://ask.adaptec.com/.

North America

- Visit our Web site at http://www.adaptec.com/.
- For information about Adaptec's support options, call 408-957-2550, 24 hours a day, 7 days a week.
- To speak with a Technical Support Specialist,
 - For hardware products, call 408-934-7274, Monday to Friday, 3:00 am to 5:00 pm, PDT.
 - For RAID and Fibre Channel products, call 321-207-2000, Monday to Friday, 3:00 am to 5:00 pm, PDT.

To expedite your service, have your computer with you.

• To order Adaptec products, including accessories and cables, call 408-957-7274. To order cables online go to http://www.adaptec.com/buy-cables/.

Europe

- Visit our Web site at http://www.adaptec.com/en-US/_common/world_index.
- To speak with a Technical Support Specialist, call, or email,
 - o German: +49 89 4366 5522, Monday-Friday, 9:00-17:00 CET, http://ask-de.adaptec.com/.
 - French: +49 89 4366 5533, Monday-Friday, 9:00-17:00 CET, http://ask-fr.adaptec.com/.
 - English: +49 89 4366 5544, Monday-Friday, 9:00-17:00 GMT, http://ask.adaptec.com/.
- You can order Adaptec cables online at http://www.adaptec.com/buy-cables/.

Japan

• Visit our web site at http://www.adaptec.co.jp/.

• To speak with a Technical Support Specialist, call +81 3 5308 6120, Monday-Friday, 9:00 a.m. to 12:00 p.m., 1:00 p.m. to 6:00 p.m.

Copyright © 2003 Adaptec Inc. 691 S. Milpitas Blvd., Milpitas CA 95035 USA.

All rights reserved.

You are permitted to redistribute, use and modify this README file in whole or in part in conjunction with redistribution of software governed by the General Public License, provided that the following conditions are met:

- 1. Redistributions of README file must retain the above copyright notice, this list of conditions, and the following disclaimer, without modification.
- 2. The name of the author may not be used to endorse or promote products derived from this software without specific prior written permission.
- 3. Modifications or new contributions must be attributed in a copyright notice identifying the author ("Contributor") and added below the original copyright notice. The copyright notice is for purposes of identifying contributors and should not be deemed as permission to alter the permissions given by Adaptec.

THIS README FILE IS PROVIDED BY ADAPTEC AND CONTRIBUTORS AS IS AND ANY EXPRESS OR IMPLIED WARRANTIES, INCLUDING, BUT NOT LIMITED TO, ANY WARRANTIES OF NON-INFRINGEMENT OR THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE DISCLAIMED. IN NO EVENT SHALL ADAPTEC OR CONTRIBUTORS BE LIABLE FOR ANY DIRECT, INCIDENTAL, SPECIAL, EXEMPLARY, OR CONSEQUENTIAL DAMAGES (INCLUDING, BUT NOT LIMITED TO, PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES; LOSS OF USE, DATA, OR PROFITS; OR BUSINESS INTERRUPTION) HOWEVER CAUSED AND ON ANY THEORY OF LIABILITY, WHETHER IN CONTRACT, STRICT LIABILITY, OR TORT (INCLUDING NEGLIGENCE OR OTHERWISE) ARISING IN ANY WAY OUT OF THE USE OF THIS README FILE, EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE.