| Q_1Q_0 | | | | | | |
|----------|----|----|----|----|--|--|
| W | 00 | 01 | 11 | 10 | | |
| 0 | 0 | 0 | X | 0 | | |
| 1 | 1 | 0 | X | 0 | | |

Figura 1: Q_0 : Máq. de Moore

| Q_1Q_0 | | | | | | |
|----------|----|----|----|----|--|--|
| W | 00 | 01 | 11 | 10 | | |
| 0 | 0 | 0 | X | 0 | | |
| 1 | 0 | 1 | X | 1 | | |

Figura 2: Q_1 Máq. de Moore




Figura 3: Z: Máq. de Moore