

No	Activity	Hazard	Person(s) in Danger	Control Measures	Residual Risk Rating
33	Working over water	Working over Water  Potential for employee to fall in water	Employee	<ul> <li>Pump out water and remove the risk where practicable.</li> <li>Always dewater.</li> <li>Where water cannot be removed, ensure completion of a detailed risk assessment.</li> <li>Ensure provision of adequate guardrails and toe boards.</li> <li>Ensure provision of safety nets where required.</li> <li>Ensure provision of safety harnesses / life lines.</li> <li>Ensure provision of suitably rated life jackets.</li> <li>Rescue lines to be available at suitably positioned points.</li> <li>If deemed necessary ensure provision of rescue craft.</li> <li>No lone working.</li> <li>If aerated water seek advice from line manager. Specialist equipment to be used for non-buoyant water.</li> </ul>	Low