

No	Activity	Hazard	Person(s) in Danger	Control Measures	Residual Risk Rating
30	Loading and unloading vehicles	Loading and Unloading Vehicles Employees and loads falling from vehicle	Employees, other contractors and public	 Lifting operations not to be carried out unless at the correct standoff distance from any overhead electricity cables and poles / pylons. Reversing vehicles shall have a banks person where required. Cordon area off where lifting operations are to take place. High visibility jacket and hard hats to be worn. Provide suitable operator access and egress to the rear of lorry loaders / vehicles. Adequate deployment of outriggers. Check ground compaction. Operator to be CPCS / NPORS or ALLMI qualified. Driver to position their self to avoid being injured by equipment or road traffic. Vehicle to be loaded / unloaded with proprietary chains and lifting beams, ensuring locking collar or D-shackle is secure. All proprietary equipment to be tested and in-date and rated appropriately for task. All loads to be chocked / secured at 	Low

Version 01

Generic Risk Assessments for work on or around the



	all times at ground level and secured	
	on the vehicle.	
	- Demarcate the working area to keep	
	members of public and unauthorised	
	persons out of the work area.	
	- Assess work area and apply	
	additional control measures for	
	unstable ground / sloping surfaces.	