

No	Activity	Hazard	Person(s) in Danger	Control Measures	Residual Risk Rating
35	All work activities that requires the lighting of the work area	Lighting Poor visibility increasing potential for accident / incident	Employees, other contractors and public	 Use of natural lighting should be used where reasonable to do so. Adequate lighting should be provided to all areas and especially to those areas used in the hours of darkness, or where work may be carried out in poor visibility or diminished lighting conditions. As a minimum, lighting should be provided for junctions, around plant and buildings, pedestrian routes and areas where loading / unloading is to be carried out. 	Low