

No	Activity	Hazard	Person(s) in Danger	Control Measures	Residual Risk Rating
52	All work activities	Site Security Risk of interference with plant and equipment, Entering excavations	Employees, other contractors and public	 Exclude all non-relevant personnel from the site. Erect secure fencing panels with warning signs. All plant to be made safe with keys removed whilst not in use. Cover deep excavations where appropriate. Make safe ladders to prevent use. Assess for additional security lighting. 	Low