
ALWAYS

- Ensure you sign / log in on arrival.
- Undertake a site specific risk assessment.
- Ensure you are trained, authorised and competent to undertake the task.
- Ensure the correct personal protective equipment (PPE) is worn at all times.
- Ensure correct plant / apparatus has been identified and proved DEAD before work commences.
- Ensure ALL members of the working party are communicated with on the task, associated risks and control measures.
- Ensure each member of the working party sign on to the appropriate safety documentation as evidence of understanding and communicate any changes where appropriate.





- Enter site without signing in / logging on.
- Continue with work activities if you do not agree with the safe systems of work (risk assessments and method statements), STOP and REPORT this to your line manager.
- Enter restricted areas without authorisation.
- Work on or interfere with equipment / apparatus if you are not trained, competent and authorised to do so.
- Remove personal protective equipment while working on site.
- Assume equipment is electrically and kinetically DEAD after being isolated, always confirm with the Competent Electrical Person on site.

ALWAYS ASSESS THE SITE FOR POTENTIAL HAZARDS BEFORE UNDERTAKING ANY WORK ACTIVITY

