

No	Activity	Hazard	Person(s) in Danger	Control Measures	Residual Risk Rating
69	All work activities within BT exchanges	Openreach Exchanges Use of ladders / soldering irons / general exchange operation	Employees and other contractors	 On arrival at a site unlock / lock the gates, with the security key provided. Gain entrance to the Exchange using OBASS card supplied by BT security (no tail gating). Sign in the exchange dairy, including the time of arrival (if the diary is not available record the information on the Risk Assessment). Carry out the full Risk Assessment and record finding(s) as appropriate. 	Low
		- First Aid Kit availability Operatives hold correct qualifications and accre - All equipment is in goo order.		 Fire exit door. Ladder test date. Levels of lighting. General environment. General tidiness of the floor. First Aid Kit availability. Operatives hold correct licenses, qualifications and accreditation. All equipment is in good working 	



	- Ensure soldering irons are locat	ed in
	the holders provided.	
	- Never stand on a ladder whilst	
	ladder is in motion.	
	- Wear all appropriate PPE (MTS	
	minimum standards).	

Generic Risk Assessments for work on or around the Telecommunications Network