

No	Activity	Hazard	Person(s) in Danger	Control Measures	Residual Risk Rating
54	All work activities	Pust  Respiratory problems / irritation to eyes	Employees, other contractors and public	<ul> <li>Eliminate the need to produce dust.</li> <li>Ensure use of water based dust suppression equipment.</li> <li>Appropriate Personal Protective Equipment and Respiratory Protective Equipment to be used.</li> <li>Eye protection at all times.</li> <li>Adequate ventilation and extraction to be used.</li> <li>Screens to be used to contain dust where appropriate.</li> </ul>	

Generic Risk Assessments for work on or around the

Telecommunications Network