#### Morrison Telecom Services

#### Team Brief







#### Agenda







2020 Overview

COVID-19

**Incident Reporting** 

.....

Incidents – Guarding of Work Areas

......

## 2020 Overview

#### 2020 Overview







#### How was our safety performance last year?

- 1 x Lost Time Incident i.e. where someone was off work due to an event that occurred at work.
- 11 x Non Lost Time Incidents i.e. minor injuries not requiring time off work.
- 85 x minor motor vehicle incidents.
- We need to improve on these
- Utility damages reduced from 2019
- This is great news and shows we are heading in the right direction
- Site reporting such as hazards and near misses and use of the Site Observation Record app was much improved.
- You will see a lot more communication on this during 2021

### COVID-19

#### COVID-19








As we are in a national lockdown, remember that the Social Separation and Hygiene Rules are still in place.

If you require a copy, please refer to your line manager.



# Incident Reporting

#### Incident Reporting







When an incident occurs on site such as an accident, serious near miss or member of public incident, it must be reported to the incident line.

Any such events notified to us by Highway Authorities or Openreach, must be reported to the incident line.

This ensures that a record of the incident is maintained and enables notification to the relevant persons to enable an investigation to commence.

We have experienced streetworks non-compliance reports raised by Openreach that have not been reported to the incident line. As soon as we are aware of it, it must be reported. **Incident Line:** 

0330 123 1092

### Incident

# Guarding of Work Area 1

#### What Happened?








- A team was observed by a Highways Inspector de-watering a chamber in the carriageway at a three-way junction without adequate traffic management.
- The work vehicle was parked partially on the footway without barrier protection and signage, whilst obscuring the vision of approaching traffic.





#### Why Did it Happen?







- Insufficient risk assessment not all controls recorded.
- Work anticipated to be of short duration, hence vehicle parked partly on the footway and inadequate traffic management.
- On previous visits to the site, the work was contained in the footway and was not anticipated to be in the road.
- Team was keen to complete the work that day.
- A water test was not undertaken before dewatering.

#### What Can We Learn?







- A suitable risk assessment must be completed for all jobs.
- If you need help completing risk assessments, refer to your line manager or SHEQ Advisor.
- Ensure you are using the risk assessment app and not the paper version. Refer to your line manager or SHEQ Advisor if you need help.
- Regardless of the time the job will take, always ensure signing and guarding is set out correctly.
- Do not park vehicles illegally; always find a safe place to park.
- If the scope of the work changes and therefore permit conditions change, stop work and consult your line manager.
- Water cannot be pumped without a test and with environmental controls in place.

### Incident

# Guarding of Work Area 2


#### What Happened?







- A team was observed by a representative of Openreach undertaking works whilst failing to provide adequate protection of the work area.
- A gas test was not undertaken.
- The work vehicle was parked on double yellow lines.
- When challenged, it was alleged that the team was not cooperative.
- Insufficient PPE was worn.



#### Why Did it Happen?







- Work was anticipated to be of short duration, so the team parked on double yellow lines, did not undertake a gas test and did not wear all appropriate PPE.
- The wind was deemed too strong to erect gate guards.
- Controls highlighted on the risk assessment to refer to the line manager when working in strong winds were not followed.

#### What Can We Learn?







- Regardless of the time the job will take, always ensure signing and guarding is set out correctly. If the weather will prevent the work being done safely, stop and consult your line manager.
- A gas test must always be undertaken when opening boxes and chambers, no matter how long the job will take.
- All appropriate PPE must be worn at all times.
- If the risk assessment results in a medium risk, the line manager must be informed, to provide guidance.
- When challenged by a third party, always remain calm and professional. If you are unsure what to say or feel vulnerable, contact your line manager.

#### What Can We Learn?







- We are seeing an increasing number of signing, lighting and guarding issues being raised by local authorities and Openreach.
- An underlying factor, as can be seen from the two examples, is that there is a belief that a short duration job can be done without the controls in place. We all know that this is not the case – so why do it?
- It is a legal requirement under the New Roads and Streetworks Act to ensure all works are appropriately guarded.
- We need to change our mind-set now, before one of us is seriously injured.

#### Thank You







Thank you for taking the time to read this team brief.

If you have any questions, please refer to your line manager or SHEQ Advisor.