# openreach

ISIS practice For Openreach people & our Partners

EPT/OHP/C031

Issue 16, 27-Jan-2023 Use until 27-Jan-2025

Published by Openreach Access Engineering & Innovation (AE&I)

Privacy- None

# Working On D Poles, Including Joint User Poles

# About this document ...

#### **Author**

The author of this document may be contacted at:

Wesley Grantham
Fibre & DSL Detailed Solution Design Professional
Openreach (BOI)
Post Point BY2Grimsby Pyewipe TEC
Estate Road No. 2
South Humberside Ind Est
Grimsby
DN31 2TJ

Telephone: +447736637011

Fax:

Email: wesley.grantham@openreach.co.uk

## **Content approval**

This is the Issue 16 of this document.

The information contained in this document was approved on 27-Jan-2023 by Anthony Stewart, Desk Engineer Co-ordinator

# **Version History**

Version No.	Date	Author	Comments
Issue 16	27-Jan-2023	Wesley Grantham	Changes made to section 3
Issue 15	06-Oct-2022	Wesley Grantham	Note added in table 1 –
			Lamppost style Hollow poles
Issue 14	01-Mar-2021	Wesley Grantham	Minor mods to table 1 & Sec
			3.3.1 for PIDOC Poles. Also,
			flowchart added at Appx 1.
Issue 13	08-Feb-2021	Wesley Grantham	Significant review and edit
			of document.
Issue 12	08-Jul-2020	Wesley Grantham	Change of Author only
Issue 11	16-Aug-2018	Chief Engineer's Office	Minor change to wording in
		Technical Documentation	sec 6 (1.). Also PECO Tel
		Team	No's updated.
Issue 10	10-Feb-2016	Chief Engineer's Office	AEC B201 incorporated into
		Technical Documentation	amended section 10. GB.
		Team	
Issue 9	03-Mar-2015	Document Manager T	Document migrated onto
			new platform with no
			content change
Issue 9	21-Jul-2011	Chief Engineer's Office	Section 8.14 added and
		Technical Documentation	Section 3 updated with AEC
		Team	B050 FTTP apparatus
			clarification. DCC1373/SH.
Issue 8	15-Feb-2011	Chief Engineer's Office	Document reviewed.Section
		Technical Documentation	8 revised. (DCC1161PD)
		Team	
Issue 7	29-Oct-2010	Chief Engineer's Office	Sections 6, 8.10.1 and 8.12.1
		Technical Documentation	(8.11 tidied) - EM 17/2010
		Team	incorporated. DCC916/SH.
Issue 6	17-Nov-2009	Chief Engineer AEI Technical	Document reviewed.
		Documentation team	(DCC425)
Issue 5	9-Dec-2008	Chief Engineer AEI Technical	Change of author and
		Documentation team	approver. Reviewed with no
			changes to content.
Issue 4	3-Oct-2007	Paul Downes	Section 8.10 amended,
			Sections 8.10.1 & 8.10.2
			added - Revised guidance
			for DNO owned poles
			classified 'S'
Issue 3	1-May-2007	Paul Downes	Document Review
Issue 2	12-May-2006	Paul Downes	Revised wording in 8.6 to
			cover adjacent D poles
			when part of an aerial cable
			route
Issue 1	19-Nov-2004	John Pearson	First issue

#### Table of Content

1	INTRODUCTION	5
2	SCOPE	5
3	WORKING ON BT OWNED D POLES	5
3.1	IMPORTANT CHECKS PRIOR TO WORK	5
3.2	Range of work permitted	· 6
3.3		
3.4		
3.5	WORKING ON DNO OWNED "D" AND "S" JOINT USER POLES	10
4	D POLE RENEWAL WORK (BT 'D' POLE)	11
4.1		
4.2	REMOVING EXISTING WIRES & CABLES	12
4.3	Transfer of wires & equipment from DNO owned Joint User Poles	15
4.4	RELEVANT ISIS DOCUMENTATION	15
5	APPENDICES	16
5 1	APPENDIX 1 — FLOWCHART FOR CAT A WORK	16

## 1 Introduction

This document details the procedures to be followed when work is required to be undertaken on D poles.

The content is split into two main parts:

Section 3 - Working on D Poles

Section 4 - Renewal of D Poles

# 2 Scope

#### BT "D" Poles:

These are poles which have been tested and found "D" by a designated Openreach Pole Tester. In almost all cases, they will be recorded on the Artisan system and have a red "D" label attached.

#### **DNO owned Joint User D Poles:**

These will not be recorded as "D" on Openreach systems, but will be similarly marked with a Red D Label.

Caution: Poles marked "D" must not be climbed!

*Note:* Whenever the word 'dropwire' is mentioned within this document it refers to both copper and fibre.

# 3 Working on BT owned D Poles

### 3.1 Important Checks Prior to Work

Prior to starting any work on a D Pole, a full <u>On-site Risk assessment</u> must be undertaken.

It is also necessary to understand the reason why the Pole has been declared "D" as that will determine the level of work permitted.

Pole status information can be obtained via the Artisan system. Or, alternatively by contacting the Network Assurance Operations Control (Tel 0330 123 3304 – Option 1-1), quoting the Exchange, DP / Carrier Pole Number and requesting the specific test result for the pole in question.

A typical test result would be D – DEC, which would indicate that the pole has been made D for Decay. The tables below detail the various test results and associated levels of work permitted for each category.

#### **UNCONTROLLED IF PRINTED**

Working On D Poles, Including Joint User Poles
Working on BT owned D Poles

Where the D Pole is a Joint User type and owned by the DNO. The DNO should be approached to check the status and to confirm the level of work permitted.

### 3.2 Range of work permitted

Once the D test result has been ascertained for the pole in question, use tables 1, 2 & 3 (below) to identify the level of work that is permitted.

The permitted works fall into two main categories.

- A. Test and repair work, removal or replacement of existing Blocks / CBT's / Joint's and the <u>replacement</u> of Dropwires (Copper or Fibre) and Aerial Cables.
- B. <u>Addition</u> of new equipment Blocks / CBT's/ Joints and Dropwires (Copper or Fibre), but not Aerial Cable.

#### Important!

Work may only be carried out where the relevant pre-requisite conditions have been met.

See section 3.3 for those conditions.

*Note:* Poles recorded as D DEC should be treated as Cat A regardless of any notes indicating TNC process.

Pole label	Test result	Description	Permitted works	Renewal policy
D D	COR	Corrosion (Hollow Pole)  Decay	(A) Test / Repair + Replacement of	Included in Asset Assurance
D D	DAM DMO	Damage - move	existing Blocks, CBT's, Joint's, Dropwires & Aerial Cable	program.  NB: These are
D	NOR	No repair possible (Damage)	Aeriai Cable	known as Policy Poles.
D	RPD	Recover pole - defective		
D	*COL	Priority 1&2 (PIDOC)		
D	*DOC	Priority 3 (PIDOC)		

<sup>\*</sup> Dropwire / Aerial Cable replacement work is excluded from permissions for COL & DOC (PIDOC) Poles. However, other Cat (A) type work is permitted.

Note: For lamppost style Hollow Poles: wires or cables must not be installed, removed or re-tensioned. For further information see EPT/OHP/C022.

#### Table 1

			1	
Pole label	Test result	Description	Permitted works	Renewal policy
D	UNS	Unstable	(A) Test / Repair + Replacement of existing Blocks, CBT's, Joint's, Dropwires & Aerial Cable	Non AAP Policy Poles. Driving program to fund pole renewal (if required).

#### Table 2

Pole label	Test result	Description	Permitted works	Renewal policy
D	UTT	Unable to Test	(A) Test / Repair +	Non AAP Policy
D	UNR	Pole damaged – Repair possible	Replacement of existing Blocks,	Poles.  Driving program
D	DEP	Depth	CBT's, Joint's, Dropwires &	to fund pole renewal (if
SD	SD	Shallow depth	Aerial Cable	required).
D	TNC	Tested not climbed	<b>(B)</b> Provision of	

#### **UNCONTROLLED IF PRINTED**

Working On D Poles, Including Joint User Poles
Working on BT owned D Poles

	new / additional	
	equipment inc	
	Blocks, CBT's and	
	Dropwires, but	
	<b>not</b> Aerial Cable	

Table 3

### 3.3 Mandatory conditions for Permitted Works

See relevant conditions for Cat A & B work below.

Note: Note: In all cases, access to the Pole is by MEWP or Scaffold only!

#### 3.3.1 Cat A - Test, Repair & Replacement work

In cases where the D test result indicates that Test, Repair and Dropwire / Aerial cable replacement work is possible, the work may be undertaken, subject to the following conditions:

- Site specific risk assessment has not identified any circumstances, which may make work unsafe
- For work involving replacement of a Dropwire or Aerial Cable A Visual, Hammer and Probe test does not indicate that Pole has become in danger of collapse. Also, a prework label is attached to the pole
- The pole is only accessed by MEWP or Scaffold. Under no circumstances should a ladder be placed against it
- Caution is taken to ensure that the pole is not hit or jarred by the MEWP
- No removal of wires that appear to be providing critical support to the Pole (without Temp stay being provided)
- Important Any Aerial cable being recovered as part of replacement work, is detensioned slowly, not bolt cropped!
- Renewal of Aerial Cable is like for like only (by Pair count)
- Any Aerial cable which is replaced, is recovered immediately, not left in place (No significant permanent change of loading introduced)
- Red A558 label shows the last inspection to be within the last 36 months
- The Aerial cable requiring renewal is not 50/0.9, 60/0.9, 100/0.6 & 104/0.9
- Aerial cables which have been brought down by trees are excluded from this procedure

Note: A Flowchart explaining the decision path for Cat "A" works is shown in Appendix 1.

#### 3.3.2 Cat B - Provision of additional equipment (inc Dropwires)

Where the D test result indicates that it is possible to add equipment. Then in addition to Cat A work, new equipment – Blocks, CBT's and Dropwires (but not Aerial cables), may also be added, subject to the following conditions:

- Site specific risk assessment has not identified any damage or other circumstances, which may make work unsafe
- The pole is subject to a successful on the day standard hammer test (no decay identified)
- A Pre-Work check label is completed and attached to the pole
- The pole is only accessed by MEWP or Scaffold. Under no circumstances should a ladder be placed against it
- Caution is taken to ensure that the pole is not hit or jarred by the MEWP
- No removal of wires that appear to be providing critical support to the Pole
- Where, using an angle finder app, the pole is shown to be leaning by more than 10°, no additional wires are to be added.
- With any new wires added, the total number of wires on the pole does not exceed those shown in the tables below

## 3.4 Maximum wire loadings

#### 3.4.1 Radially distributed poles

The total wire count (existing + added wires) must not **exceed** 75% of the normal maximum load of the pole - See Table below.

Pole Category	Light Poles		Medium Poles		Stout Poles	
	Original max loading	75% of max loading	Original max loading	75% of max loading	Original max loading	75% of max loading
1- urban terraced	40	30	40	30	50	37
2- urban semi -detached	28	21	40	30	50	37
3 – semi rural	24	18	40	30	50	37

Working On D Poles, Including Joint User Poles
Working on BT owned D Poles

4 - rural	20	15	30	22	40	30
5 – exposed rural	12	9	20	15	30	22

Table 4

#### 3.4.2 Non-Radial (One side loaded) Poles

Non-radial poles are defined as those where all wires are attached in a single 180° Arc, with zero wires in the opposing arc. The overall standard wire loading limits are shown below and should not be exceeded.

Pole Class	Light	Medium	Stout
Max wires	7	15	30

Table 5

#### 3.4.3 Emergency Work (Radial & Non Radial)

The introduction of additional loadings beyond the limits shown in Tables 4 & 5 are not permitted. The only exception being Emergency Work, which is defined as work for hospitals, ambulance, police, fire or similar circuits.

Commercial necessity is <u>not</u> a valid reason for carrying out work classified as an emergency.

## 3.5 Working on DNO owned "D" and "S" Joint User poles

**DNO D Pole** – The pole may only be accessed using a MEWP and permitted works shall not exceed those described as Category A in section 3.2 above. Follow the conditions shown in \*3.3.1 above.

Where it is required to provide new equipment (Category B work), you must first contact the DNO and seek their authorisation. Under no circumstances should additional plant be added without such authorisation. Follow the conditions shown in \*3.3.2 above.

**DNO "S" Pole** - Some (but not all) DNO's use "S" to indicate "suspect". For these Poles, check with the DNO and confirm that access is allowed. If yes, ascertain the level of work permitted and follow the relevant conditions laid down in \*3.3.

#### Important!

<sup>\*</sup>Excludes the requirement to fit a Pre-Climb check label.

Working On D Poles, Including Joint User Poles

- Only where the test shows the pole to be OK may it be accessed using a Ladder insulated 7A (Blue ladder).
- Regardless of the method of access, all DNO Poles require two persons working

#### 3.5.1 **Current Joint Use D Pole in Imminent Danger of Collapse**

If following a hammer test, it is genuinely suspected that a DNO Pole is in imminent danger of collapse.

- Do not attempt to access it (Even by MEWP)
- Contact and advise the local DNO

#### **Contacting the local DNO:**

From a Mobile phone – Dial 105.

Web: https://www.energynetworks.org/operating-the-networks/whos-my-networkoperator

#### 3.5.2 Ex Joint User Pole with only BT Plant, in Imminent Danger of Collapse

Where the pole is an Ex-joint user pole with only BT plant present, and is in imminent danger of collapse, the current Priority D Pole Process for BT poles must be followed. Works teams (DL or Contract) should carry out any work to replace or recover the D pole in the manner described within section 4 of this document.

# D Pole Renewal Work (BT 'D' Pole)

#### 4.1 **General principles**

- Work must be undertaken in accordance with the rules laid out in this document.
- Anyone involved must be suitably trained to carry out the task.
- An on-site risk assessment must be completed prior to commencement of work.

#### Work to renew a D pole can be split into 4 parts:

- Removing the existing wires and cables from the D pole.
- Recovery of the D pole.
- Provision of the new pole.

■ Reconnecting the wires & cables to the new pole.

## 4.2 Removing Existing Wires & Cables

The first determining factor on how the work should proceed will depend on whether the new pole is to be planted in the same hole, or if it is to be planted alongside the existing D pole.

#### 4.2.1 Pole to be planted in Same Hole (Dropwires only)

All of the wires will need to be disconnected from the D pole and laid out in a safe and suitable manner. Before starting work, consideration must be given to how the loading of the pole will change during the duration of this work. When the pole is radially loaded, the wires should be disconnected in a way that gradually reduces the number, without leaving an excessive load in one direction – see attached Fig 1 and suggested sequence.




Fig 1
A suggested de-tensioning sequence for a pole with 20 wires would be:

D Pole Renewal Work (BT 'D' Pole)

1, 11, 15, 5, 9, 18, 3, 12, 10, 19, 13, 4, 7, 16, 20, 14, 6, 17, 2, 8

A similar principle should be used for other quantities

If the pole has the majority of wires within a  $180^{\circ}$  arc or similar side loading, then refer to Fig 2.




Fig 2

A suggested de-tensioning sequence for a pole with 10 wires (single side loading) would be:

2, 9, 5, 7, 3, 8, 4, 6, 1, 10 again with a similar principle for other quantities.

The appropriate method for laying out the wires should be determined on-site. This may involve coiling the wires and leaving in the gardens, or temporarily attaching to the Dropwire fixing point on the house. However this is achieved, the working party must ensure that the wires are safe for the duration of the works. Any wires that need to be changed, either because they are obsolete or faulty, or will not reach to the new pole position or for any other reason should be completely recovered.

Note: Dropwires must not be disconnected from the house or building end, must not be left laid in the carriageway and must be coiled up to avoid causing a trip hazard.

# 4.2.2 Pole to be planted in Same Hole or Alongside Existing Pole (with Aerial Cables)

The procedure for de-loading / re-loading / transferring Dropwires is as described above.

Where an Aerial Cable spans to the next pole on route, which is also D, the following two options apply.

- 1. Renew that pole too
- 2. Alternatively, the Pole may remain in-situ, providing that before work begins it is subject to an assessment, to gauge whether it is sufficiently stable to withstand the temporary change in loading caused by lowering of the Aerial Cable from the pole being renewed.

#### For option 2, the following mandatory conditions apply:

- A Site Specific Risk Assessment does not identify any damage or other circumstances, which may make work unsafe
- A standard Hammer test of the Pole does not indicate that it is seriously decayed, or in a Pole In Danger Of Collapse (PIDOC)

Additionally, if the Pole needs to be accessed:

- A Pre-Climb / Work check is completed and label attached to the pole
- Access is made by MEWP or Scaffold only
- Caution is taken to ensure that the pole is not hit or jarred by the MEWP
- No lowering of the Aerial Cable if it appears to be providing critical support to the Pole
- Aerial cable is de-tensioned slowly, not bolt cropped
- If renewal of the Aerial Cable is required, this is done on a like for like basis only (i.e. Lightweight for Lightweight)
- Any Aerial cable replaced, is recovered immediately, not left in place (No significant permanent change of loading introduced)

Where these conditions cannot be met, then temporary staying of the adjacent pole must be considered, in order to support it whilst work to renew the first pole is being carried out.

Detail on providing temporary support for the pole can be found in ISIS EPT/OHP/B038. The level of temporary support should be commensurate with the loading. For example, A Lightweight cable on a D pole, which only needs to be supported for the short duration whilst the cable is lowered / re-attached to the new pole, may only require the use of 1 or 2 Crowbars.

# 4.3 Transfer of wires & equipment from DNO owned Joint User Poles

The DNOs use a similar pole test process and D criteria to BT. Therefore the procedures for working on BT D poles (shown elsewhere in this document) can also be applied to Joint User Poles.

#### 4.4 Relevant ISIS Documentation

Standard pole recovery & provision procedures are detailed in the following ISIS documents:

- EPT/OHP/B011 Drop wiring
- EPT/OHP/B012 Aerial Cabling
- EPT/OHP/B034 Mechanised Poling
- EPT/OHP/B036 Pole Fittings & Furniture
- EPT/OHP/B037 Manual Pole Provision
- EPT/OHP/B038 Manual Pole Recovery

# 5 Appendices

## 5.1 Appendix 1 – Flowchart for Cat A work

The Flowchart below explains the decision path where test result data indicates a Pole is suitable for Cat A Work.




Figure 3 – Cat A work flowchart

#### **END OF DOCUMENT**