


LADDERS





RISK ASSESSMENT


Inspect ladders as part of the Risk Assessment



ANGLE

A ratio of 4 up to 1 out is the

correct angle to avoid **DANGER**





Feet, Knees and Hands need to

OF CONTACT

3 POINTS


be in contact with the ladder.



DO NOT over-reach. Move the ladder to reach safely.

OVER REACH





• Ladders MUST be footed to avoid slippage. • Appropriate fallarrest equipment MUST be worn when working at

FOOT LADDER

& WEARING

HARNESS

height.

• Working at Height procedures MUST be complied with.





Ladders MUST be

tied to **avoid slippage**.





Always keep **3 steps clear** from the top when working on step ladders.



• Avoid working at height where it is reasonably practicable to do so

- Remember the Do's and Don'ts of working at height

• Use controls to prevent falls from height

• Minimise the distance and consequences of a fall

• Protect everyone at risk either (collectively or personally)





FOR MORE INFORMATION OR IF YOU HAVE ANY CONCERNS CONTACT

YOUR SHEQ DEPARTMENT

MGroupServices