

No	Activity	Hazard	Person(s) in Danger	Control Measures	Residual Risk Rating
66	All work activities	Testing of Underground Chambers Potential for the presence of gas / low oxygen	Employees and other contractors	 Ensure availability and use of GDU (Gas Detection Unit). Ensure monitor is calibrated / in date. Perform gas test just under manhole covers. Test again once cover is removed. If chamber has standing water - gas test at water level. Test on initial entry into every box and after break times if monitor has been removed for any reason. Test again at floor level once water has been removed. 	Low

Generic Risk Assessments for work on or around the

Telecommunications Network