

No	Activity	Hazard	Person(s) in Danger	Control Measures	Residual Risk Rating
53	All work activities Lighting and ventilating in gaseous atmosphere	Risk of Gas Explosion through Ignition	Employees, other contractors and public	 Check area for presence of gases with gas monitor. Ventilate area prior to entering. Always use intrinsically safe lighting, torches and blowers. 	Low

Generic Risk Assessments for work on or around the

Telecommunications Network