

| No | Activity | Hazard | Person(s) in Danger | Control Measures | Residual Risk Rating |
|----|----------|----------------------------|---------------------------------|--|-------------------------|
| 64 | Poling | Poling – Working at Height | Employees and other contractors | Ensure the Land Owner has given permission for you and your vehicle. Always check cable for damage prior to commencing work. Always test poles before climbing. Use mechanical access whenever possible. Free Climbing not permitted at any time. Do not carry equipment up ladders. Do not over reach Ensure the ladder is at the correct angle and is tied at the fourth rung, lashed at the top. | Low |

Generic Risk Assessments for work on or around the

Telecommunications Network