Low Voltage activities in normal circumstances are undertaken 'LIVE' this is to maintain customer / property supplies; following correct 'LIVE' working techniques and adherence to your Competency Authorisation will maintain safety from the network whilst undertaking this activity.

Before any Low Voltage Activities are completed ensure the cable / line / network to be worked on is positively identified in accordance with the approved Procedure.

- All persons working on any Low Voltage Network SHALL be trained, have sufficient technical knowledge and be authorised in writing for the activity to be undertaken.
- All persons carrying out 'LIVE' working Activities SHALL be accompanied by a craftsperson(s) mate (Including Support Person) who has been trained and authorised in writing. They SHALL have sufficient knowledge of the correct rescue procedure in the event of an emergency situation.
- All Persons SHALL Work in accordance with the Telecom Division and / or client Distribution Safety Rules and Operational Procedures



- In addition to the standard Telecom Division Personal Protective Equipment the wearing of a Full Face Visor and the correct Low Voltage insulated gloves (Live Working) SHALL be worn.
- All newly installed cables SHALL be tested for insulation and continuity before they are connected to the Network.
- All phases SHALL be individually / suitably shrouded before connecting any phase connector and SHALL only be removed one at a time.
- All tools and equipment MUST be insulated and in accordance with the Telecom Division tooling list.

IF UNSURE STOP WORK AND SEEK ADVICE FROM YOUR LINE MANAGER