

No	Activity	Hazard	Person(s) in Danger	Control Measures	Residual Risk Rating
18	Poor housekeeping	Slips, Trips and Falls Employees and others injuring themselves through poor housekeeping	Employees, other contractors and public	 All spillages to be cleaned up immediately – use spill kit. Remove any waste materials from site immediately. Do not leave tools and equipment lying about on the floor. Store the minimum amount of materials needed on site, deliveries to be fenced off away from site so it does not cause unnecessary obstruction. Route any cables and hoses where they do not create a tripping hazard. Keep vehicles tidy. Keep boots, steps and ladders free from mud etc. Take care getting in and out of vehicles and plant. Climb down facing the vehicle, hold on, and do not jump down. Use designated walkways/access routes. Housekeeping to be maintained, area(s) to be kept clear and tidy, Additional care may be required during adverse weather conditions. 	Low