

239 LIFT_TIMEOUT
 240 HOOKSW_BINSW_MISMATCH
 241 LIFT_ENCODER_LOST_SIGNAL
242 UNSTABLE_LIFT

Última actualización: 27/8/2024, 18:31:21

Error de elevación

Explicación

El robot ha detectado que la velocidad de elevación se está desviando de la velocidad esperada.

Causa

El cable del codificador está suelto o desconectado

Acción

Compruebe que el cable del codificador del ascensor esté enchufado correctamente

Enchufe el cable del codificador del ascensor

243 BOTTOM_DETECTED_PASSING_GRID_TRACKS

Notificación de robot

1 LIFT_SKEW_01
 2 LIFT_SKEW_02
 3 LIFT_SKEW_03
 4 LIFT_SKEW_04
 5 LIFT_SKEW_05
 6 LIFT_SKEW_06
 7 LIFT_SKEW_07
 8 LIFT_SKEW_08
 9 LIFT_SKEW_09
 10 LIFT_SKEW_10
 11 LIFT_SKEW_11
 12 LIFT_SKEW_12
 13 LIFT_SKEW_13
 14 LIFT_SKEW_14
 15 LIFT_SKEW_15
 16 TEMPORARILY_REDUCED_ACCELERATION_10
 17 TEMPORARILY_REDUCED_ACCELERATION_09
 18 TEMPORARILY_REDUCED_ACCELERATION_08
 19 TEMPORARILY_REDUCED_ACCELERATION_07
 20 TEMPORARILY_REDUCED_ACCELERATION_06
 21 TEMPORARILY_REDUCED_ACCELERATION_05
 22 TEMPORARILY_REDUCED_ACCELERATION_04
 23 TEMPORARILY_REDUCED_ACCELERATION_03
 24 TEMPORARILY_REDUCED_ACCELERATION_02