Date:09/10/2022 07:41AM

## Pre Scan Vehicle Sysytem Report

## **Vehicle Information**

MAKE Toyota
YEAR 2021
MODEL Highlander
ENGINE 3.51, V6 MI

ENGINE 3.5L V6 MFI (2GR-FKS)

Blind Spot Monitor Slave: 0
Blind Spot Monitor Master: 0
Heating & Air Conditioning: 0

Master Switch Module: 0

SYSTEM CodeScan

REN

CODE SCAN RESULTS

Systems Analyzed:34

Engine: 0 Transmission: 0 Brake/Electric Parking Brake: 0 Instrument Panel Cluster: 0 Radar Cruise 1: Telematics: 0 Stop and Start: 0 Front Radar Sensor: 0 Front Recognition Camera: 0 Front Recognition Camera (Front Lighting Control): 0 Lane Control: 0 Pre-Collision: 0 Radar Cruise 2: 0 Road Sign Assist: 0 Airbag: 0 Body Control Module: 0 O Door Motor Modules: Door Motor: 0 Open Motor Modules:Door Motor: 0 O Door Motor Modules:Door Motor: 0 Open Motor Modules:Door Motor: 0 Central Gateway: 0

Power Source: 0

Smart Key Access: 0

Starting Control: 0

Tire Pressure Monitor: 0

Electric Motor Power Steering: 0

Navigation System: 0

Occupant Classification: 0

Steering Angle Sensor: 0

Sliding Roof: 0

OBDII Codes (\$03): 0

OBDII Permanent Codes (\$0A): 0

## **Readiness Monitors**

## **Tests Complete**

Misfire

Fuel System

Comprehensive Component

**⊘** EGR/VVT

Catalyst

Evaporative System

Oxygen Sensor

Oxygen Sensor Heater