Date:09/10/2022 07:59AM

Post Scan Vehicle Sysytem Report

Vehicle Information

MAKE Nissan YEAR 2020 MODEL Altima

ENGINE 2.5L L4 (PR25DD)

SYSTEM CodeScan

REN

CODE SCAN RESULTS

Systems Analyzed:15

Engine: 0

Transmission: 0

Antilock Brakes: 2

Airbag: 1

⚠ HVAC: 2

Body Control Module: 0

Electronic Power Steering: 0

Intelligent Power Distribution Module: 0

△ Multi Audio Visual (AV): 2

Meter: 0

△ Tire Pressure Monitor: 7

Laser / Radar: 4

CAN Gateway: 0

Chassis Control: 0

⚠ Intelligent Cruise Control/Advanced Driver Assistance System 2: 5

⊘ OBDII Codes (\$03): 0

OBDII Permanent Codes (\$0A): 0

Antilock Brakes

C1108 | Front Left Sensor 2 - History Code U1000 | CAN Communication Circuit - History Code

Airbag

HVAC

B24B4-02 | Air Conditioning Control Communication - Past U1000-01 | CAN Communication Circuit - Past

Multi Audio Visual (AV)

B13D9-8F | USB Communication Error - Past B1375-11 | Rear Camera Power Supply - Past

Tire Pressure Monitor

C170400 | Left Front Low Air Pressure - History Code C170500 | Right Front Low Air Pressure - History Code C170600 | Right Rear Low Air Pressure - History Code C170700 | Left Rear Low Air Pressure - Current Code C170800 | No Data Received from Left Front - History Code C170900 | No Data Received from Right Front - History Code C176500 | Front Left Wheel Sensor - History Code

Laser / Radar

C1A16-97 | Radar Stain (Component or System Operation Obstructed or Blocked) - History Code C1A12-78 | Laser Beam Off-center (Alignment or Adjustment Incorrect) - Current Code C1A50-48 | ADAS (Advanced Driver Assist System) Malfunction (Supervision Software Error) - History Code C1A17-49 | Control Unit (Internal Electronic Error) - History Code

Intelligent Cruise Control/Advanced Driver Assistance System 2

C1A04-04 | ABS/TCS/VDC Circuit [System Internal Malfunction] - History Code
C1B82-78 | Distance Sensor Offset Center [Alignment or Adjustment Incorrect] - History Code
C1A03-62 | Vehicle Speed Sensor Circuit [Signal Compare Error] - History Code
U1502-87 | ICC Sensor CAN Communication Circuit [Missing Message] - History Code
C1A26-04 | ABS/TCS/VDC Circuit [System Internal Malfunction] - History Code

Readiness Monitors

Tests Complete

✓ Misfire✓ Fuel System✓ Comprehensive Component✓ EGR/VVT

Catalyst
Evaporative System

Oxygen SensorOxygen Sensor Heater