Date:09/12/2022 06:13AM

# Post Scan Vehicle Sysytem Report

#### **Vehicle Information**

MAKE Chevrolet
YEAR 2021
MODEL Trailblazer
ENGINE 1.3L L3 (L3T)
SYSTEM CodeScan

CODE SCAN RESULTS

**Systems Analyzed:18** 

Engine: 0

Transmission: 0

Antilock Brakes: 1

Airbag: 0

△ Body Control Module: 2

Camera System: 0

Electric Power Steering Control Module: 0

HVAC: 0

HVAC Controls: 0

Instrument Panel Cluster: 0

Keyless Entry: 0

Passenger Presence System: 0

ARadio: 3

Rear Drive Control Module: 0

Serial Data Gateway Module: 0

Serial Data Gateway Module: 0

Telematics Communication Interface: 0

Tire Pressure Monitor: 2

OBDII Codes (\$03): 0

OBDII Permanent Codes (\$0A): 0

### **Antilock Brakes**

C2A08 | Vehicle Stability Control Disabling Inhibited by Tire Pressure Monitoring (Symptom 00) - Test Failed Since DTC Clear, History DTC, Current DTC Since Power Up.

## **Body Control Module**

B3006 | Hood Ajar Circuit Short To Battery (Symptom 01) - Test Failed Since DTC Clear, History DTC. B3006 | Hood Ajar Circuit Open Circuit (Symptom 04) - Test Failed Since DTC Clear, History DTC.

## Radio

B124B | Universal Serial Bus (USB) Circuit 1 (Symptom 00) - History DTC.

B125A | Antenna Signal Circuit Short To Ground (Symptom 02) - History DTC.

B1265 | Switched 14V Short To Battery (Symptom 01) - History DTC.

## **Tire Pressure Monitor**

B3006 | Hood Ajar Circuit Short To Battery (Symptom 01) - Test Failed Since DTC Clear, History DTC. B3006 | Hood Ajar Circuit Open Circuit (Symptom 04) - Test Failed Since DTC Clear, History DTC.

## **Readiness Monitors**

#### **Tests Complete**

Misfire

Fuel System

Comprehensive Component

**EGR/VVT** 

Catalyst

Evaporative System

Oxygen Sensor

Oxygen Sensor Heater